



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:

OGM Priscilla Burton Environmental Scientist III

Inspection Report

| Permit Number: | C0070001 |
|------------------|-----------------------------|
| Inspection Type: | PARTIAL |
| Inspection Date: | Saturday, February 28, 2009 |
| Start Date/Time: | 2/28/2009 11:00:00 AM |
| End Date/Time: | 2/28/2009 3:00:00 PM |
| Last Inspection: | Wednesday, January 28, 2009 |

Inspector: Priscilla Burton, Environmental Scientist III

Weather: sun 35

InspectionID Report Number: 1929

Types of Operations

Accepted by: jhelfric

3/11/2009

Permitee: LODESTAR ENERGY INC
Operator: WILLIAM BISHOP, TRUSTEE

Site: WHITE OAK MINE

Address: 2525 HARRODSBURG RD STE 235, LEXINGTON KY 40504-1628

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

| 3,906.00 | Total Permitted | | | |
|----------|------------------------|--|--|--|
| 151.10 | Total Disturbed | | | |
| | Phase I | | | |
| | Phase II | | | |
| | Phase III | | | |

Current Acreages

Mineral Ownership

✓ Federal ✓ Underground
✓ State ✓ Surface
✓ County ✓ Loadout
✓ Fee ☐ Processing
☐ Other ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Entrance to the Belina Mine facilities is blocked by snow. A locked gate will prevent access when the snow melts. Surface ownership was researched so that the land owner could be contacted and the gate opened when the snow melts. Current plat maps were down loaded from the Carbon County web site and placed in the MRP in front of the outdated Surface Ownership Map R645-301-112.500.

Inspector's Signature

Date

Saturday, February 28, 2009

Priscilla Burton, Environmental Scientist III

Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070001 Inspection Type: PARTIAL

Inspection Date: Saturday, February 28, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | | Evaluated | Not Applicable | Comment | Enforcement |
|------|---|-----------|----------------|----------|-------------|
| 1. | Permits, Change, Transfer, Renewal, Sale | ✓ | | ~ | |
| 2. | Signs and Markers | | | | |
| 3. | Topsoil | | | | |
| 4.a | Hydrologic Balance: Diversions | | | | |
| 4.b | Hydrologic Balance: Sediment Ponds and Impoundments | | | | |
| 4.c | Hydrologic Balance: Other Sediment Control Measures | | | | |
| 4.d | Hydrologic Balance: Water Monitoring | | | | |
| 4.e | Hydrologic Balance: Effluent Limitations | | | | |
| 5. | Explosives | | | | |
| 6. | Disposal of Excess Spoil, Fills, Benches | | | | |
| 7. | Coal Mine Waste, Refuse Piles, Impoundments | | | | |
| 8. | Noncoal Waste | | | | |
| 9. | Protection of Fish, Wildlife and Related Environmental Issues | | | | |
| 10. | Slides and Other Damage | | | | |
| 11. | Contemporaneous Reclamation | | | | |
| 12. | Backfilling And Grading | | | | |
| 13. | Revegetation | | | | |
| 14. | Subsidence Control | | | | |
| 15. | Cessation of Operations | | | | |
| 16.8 | a Roads: Construction, Maintenance, Surfacing | | | | |
| 16. | o Roads: Drainage Controls | | | | |
| 17. | Other Transportation Facilities | | | | |
| 18. | Support Facilities, Utility Installations | | | | |
| 19. | AVS Check | | | | |
| 20. | Air Quality Permit | | | | |
| 21. | Bonding and Insurance | | | | |
| 22. | Other | | | | |

Inspection Continuation Sheet

Permit Number: C0070001 Inspection Type: PARTIAL

Inspection Date: Saturday, February 28, 2009 Page 3 of 3

Permits, Change, Transfer, Renewal, Sale

A locked gate will prevent access when the snow melts. Surface ownership was researched so that the land owner could be contacted and the gate opened when the snow melts. Current plat maps were down loaded from the Carbon County web site and placed in the MRP in front of the outdated Surface Ownership Map R645-301-112.500.