

0017

### Document Information Form

Mine Number: C/007/004

File Name: Incoming

To: DOGM

From:

Person N/A

Company OFFICE OF SURFACE MINING

Date Sent: September 12, 1984

Explanation:

MINE SITE EVALUATION INSPECTION REPORT.

cc:

File in:  
CI 007, 004, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date \_\_\_\_\_ For additional information

SEP 12 1984

United States Department of the Interior  
Office of Surface Mining  
Mine Site Evaluation Inspection Report

DIVISION OF OIL  
GAS & MINING

For Office Use Only

1a	1b	1c
Y Y M M	Batch	Report

2. Name of Permittee  
PRICE RIVER COAL CO

9. MSHA Number

10. Date of Inspection  
(Y Y M M D D)  
840822

3. Street Address  
P.O. Box 629

11. State Permit Number  
ACT-007-004

4. City  
HRIPER

5. State  
UT

12. Name of Mine  
BRAZTAH COMPLEX

6. Zip Code  
84526

7. Area Code  
801

8. Telephone Number  
472-3411

13. County Code  
007

14. State Code  
UT

15. Strata

16. State Area Office  
01

17. OSM Field Office No.  
02

18. OSM Area Office No.

19. OSM Sample No.

20. Type of Inspection (Code)  
SW

21. Joint Inspection  
Yes No

22. Inspector's ID No.  
032

23. Status

- A  DE Type of Permit
- B  A Mine Status (Code)
- C  20 Type of Facility (Code)
- D  02720.0 Number of Permitted Acres
- E  00144.0 Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

- A  Steep Slope
- B  Mountain Top Removal
- C  Prime Farmlands
- D  Alluvial Valley Floors
- E  Anthracite
- F  Federal Lands
- G  Indian Lands
- H  Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

Standards That Assure Reclamation Quality and Timeliness

- A  Distance Prohibitions
- B  Mining Within Permit Boundaries
- C  Signs and Markers
- D  Sediment Control Measures
- E  Design and Certification Requirements—Sediment Control
- F  Effluent Limits
- G  Surface Water Monitoring
- H  Ground Water
- I  Blasting
- J  Haul/Access
- K  Refuse Imp
- L  Other: Spe

- M  Topsoil Handling
- N  Backfilling and Grading
- O  Following Reclamation Schedule
- P  Revegetation Requirements
- Q  Disposal of Excess Spoil
- R  Handling of Acid or Toxic Materials
- Highwall Elimination
- Downslope Spoil Disposal
- Post Mining Land Use
- Cessation of Operations: Temporary
- Other \_\_\_\_\_

File in:  Confidential  
 Shelf  
 Expandable  
Refer to Record No. 0017 Date 9-12-84  
In CI 007, 004, Incoming  
For additional information

SEP 12 1984

United States Department of the Interior  
Office of Surface Mining  
Mine Site Evaluation Inspection Report

DIVISION OF OIL  
GAS & MINING

For Office Use Only

1a  
Y Y M M

1b  
Batch

1c  
Report

2. Name of Permittee

PRICE RIVER Coal Co

3. Street Address

P.O. Box 629

4. City

Hesper

5. State

UT

6. Zip Code

84526

7. Area Code

801

8. Telephone Number

472-3411

9. MSHA Number

10. Date of Inspection  
(Y Y M M D D)

840822

11. State Permit Number

ACT-007-004

12. Name of Mine

BRAZTAH complex

13. County Code

007

14. State Code

UT

15. Strata

16. State Area Office

01

17. OSM Field Office No.

02

18. OSM Area Office No.

19. OSM Sample No.

20. Type of Inspection (Code)

GW

21. Joint Inspection  
Yes No

X

22. Inspector's ID No.

032

23. Status

- A  DR Type of Permit
- B  A Mine Status (Code)
- C  20 Type of Facility (Code)
- D  02720.0 Number of Permitted Acres
- E  00144.0 Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

- A  Steep Slope
- B  Mountain Top Removal
- C  Prime Farmlands
- D  Alluvial Valley Floors
- E  Anthracite
- F  Federal Lands
- G  Indian Lands
- H  Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

- A  Distance Prohibitions
- B  Mining Within Permit Boundaries
- C  Signs and Markers
- D  Sediment Control Measures
- E  Design and Certification Requirements—Sediment Control
- F  Effluent Limits
- G  Surface Water Monitoring
- H  Ground Water Monitoring
- I  Blasting Procedures
- J  Haul/Access Road Design and Maintenance
- K  Refuse Impoundments
- L  Other: Specify \_\_\_\_\_

Standards That Assure Reclamation Quality and Timeliness

- M  Topsoil Handling
- N  Backfilling and Grading
- O  Following Reclamation Schedule
- P  Revegetation Requirements
- Q  Disposal of Excess Spoil
- R  Handling of Acid or Toxic Materials
- S  Highwall Elimination
- T  Downslope Spoil Disposal
- U  Post Mining Land Use
- V  Cessation of Operations: Temporary
- W  Other \_\_\_\_\_

United States Department of the Interior  
Office of Surface Mining  
Mine Site Evaluation Inspection Report

AG # 7

26. State Permit Number <b>ACT-007-004</b>	27. Date of Inspection (Y M M D D) <b>840822</b>
---	--

28. Yes  No  Do mining and reclamation activities on the site comply with the plans in the permit?  
If no, provide narrative to support this determination.

29. Indicate number of complete and partial inspections conducted by the State to date for this annual review period:

29a.  Number of Completes      29b.  Number of Partials

30. Indicate number of complete and partial inspections required by the State during this annual review period:

30a.  Number of Completes      30b.  Number of Partials

31. Has inspection frequency been met?

31a. Yes  No  Completes      31b. Yes  No  Partials

32. FEDERAL ENFORCEMENT INFORMATION. [Enter violation number. Check appropriate box(es)]			Violation Codes
Ten-Day Notice No.	Notice of Violation No.	Cessation Order No.	
<input type="text"/>	<input type="text"/>	<input type="text"/>	
A <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Authorizations to Operate
B <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Signs and Markers
C <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Backfilling and Grading
D <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Highwall Elimination
E <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Rills and Gullies
F <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Improper Fills
G <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Topsoil Handling
H <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sediment Ponds
I <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Effluent Limits
J <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Water Monitoring
K <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Buffer Zones
L <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Roads
M <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Dams
N <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Blasting
O <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Revegetation
P <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Spoil on the Downslope
Q <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Mining Without Permit
R <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Exceeding Permit Limits
S <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Distance Prohibitions
T <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Toxic Materials
U <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Other Violations

33. Name of Authorized Representative (print or type)  
*Dennis Griffin*

Signature of Authorized Representative <i>Dennis Griffin</i>	Date <i>8/30/84</i>	<i>00 5</i>
Signature of Reviewing Official <i>Tom [unclear]</i>	Date <i>9/2/84</i>	<i>10 0</i>
		<i>01 0</i>
		<i>00 5</i>

Minesite Evaluation Narrative Report

Price River Coal Co.  
Braztah Complex

Personnel: Donna Griffen, OSM, Rob Wiley, Price River Coal Co.  
Date: August 22, 1984.

This was a follow up inspection to verify abatement of NOV #84-2-032-I. The NOV was written following a TDN for failure to pass surface drainage through a sediment pond. The ponds (2 in series) were in place and appeared constructed to design. The Engineering certification has not been accomplished since the pond had just been finished. Survey of the pond was scheduled with the minesite surveyor, and a copy of this will be sent by the company to OSM-Albuquerque. NOV 84-2-032-1 was terminated.