



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

*File*

*John SCL*

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: March 26, 1987  
10:30 a.m. to 12:50 p.m.

Permittee and/or Operators Name: Price River Coal Company  
Business Address: P. O. Box 629, Helper, Utah 84526  
Mine Name: Willow Creek Permit Number: INA/007/002  
Type of Mining Activity: Underground  Surface  Other   
County: Carbon  
Company Official (s): Lynnette Rudman, receptionist (office only)  
State Official(s): David Lof & Rick Summers  
Partial:  Complete:  Date of Last Inspection: 12/17/86  
Weather Conditions: Overcast, cold  
Acreage: Permitted to be determined following resubmittal of Price River Coal Company's MRP. Disturbed  Regraded  Seeded  Bonded   
Enforcement Action: none.

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( X )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( X )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( X )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( X )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( X )	( )
7. COAL PROCESSING WASTE	( )	( )	( X )	( )
8. NONCOAL WASTE	( X )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( X )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( )
12. BACKFILLING AND GRADING	( X )	( )	( )	( )
13. REVEGETATION	( X )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( X )	( )
15. CESSATION OF OPERATIONS	( X )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( X )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( X )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( X )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( X )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/007/002

DATE OF INSPECTION March 26, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits. The operator has received the Division letter of 12/31/86 discussing initiation of the mid-term permit review. The operator has committed to submit an updated MRP for the Willow Creek area by June 3, 1987.


4c. Sediment Ponds. Sedimentation pond inspection reports inclusive through 2/20/87 were available in the office.

4e. Water Monitoring Water monitoring data for the third quarter (11/20/87) was available at the mine office.

Copy of this Report:

Mailed to: Donna Griffin - OSM, George Lasley - PRCC

Given to: Joe Helfrich and Sue Linner - DCGM

Inspectors Signature and Number:  #15

Date: April 24, 1987