

0006



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

gch
SCC

INSPECTION DATE & TIME: 11/15, 16 & 17/89
7:00 a.m. to 4:00 p.m. each day

Permittee and/or Operators Name: Castle Gate Coal Company
Business Address: P.O. Box 449
Mine Name: Price River Complex Permit Number: ACT/007/004
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): Tom McKenna and John McCurdy
State Official(s): Harold G. Sandbeck
Partial: XXX Complete: Date of Last Inspection: 10/13/89
Weather Conditions: Clear and cold
Acreage: Permitted 8510 Disturbed 130 Regraded 6.5 Seeded 6.5 Bonded 130
Enforcement Action: N89-27-10-7(SEE 1.)

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DIVERSIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. SEDIMENT PONDS AND IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. SURFACE AND GROUNDWATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL PROCESSING WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS				
a. CONSTRUCTION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. MAINTENANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/004

DATE OF INSPECTION 11/15, 16 & 17/89

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments: During this oversight inspection, Tom McKenna and John McCurdy accompanied the undersigned inspector on this partial inspection. The oversight OSM representatives were Rade Orell and Mitch Rollings.

1. Permits.

OSM TDN Issues

The Ten-Day Notice X-89-02-107-11-TV-4 was received by the Division on November 30, 1989. Following are the four TDN issues:

1 of 4: "Failure to obtain a permit before engaging in or carrying out underground coal mining activities. The road to the Crandall shaft facility, the road to Hardscrabble Canyon."

2 of 4: "Failure to mark the perimeter of all areas on the insides of the undisturbed diversions at Hardscrabble Canyon number 4 mine, Sowbelly Canyon diversions, and water tank road; Crandall Shaft Facility substation cut slopes".

3 of 4: "Failure to divert surface drainage from the crest and face of the coal processing waste in accordance with UMC 817.72(d). The School House Canyon coal processing waste pile."

4 of 4: "Failure to pass drainage from the disturbed area through a sedimentation pond before leaving the permit area. The middle topsoil stockpile on the Crandall shaft facility road and the substation near Goose Island at the Hardscrabble Canyon facilities."

N89-27-10-7

The violation was issued on November 17, 1989. The abatement date for all seven (7) parts is on December 18, 1989 at 5:00 p.m. See the inspector's statement which is attached to this inspection report.

Copy of this Report:

Mailed to: Tom McKenna (CGCC), Price Office and Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: Howard G. Anderson #27 Date: 12/05/89