

0004



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: September 7, 1990  
.1 hour

Permittee and/or Operators Name: Castle Gate Coal Company  
Business Address: One Riverfront Place, 20 N W 1st Street  
Evansville, IN 47708-1258  
Mine Name: Castle Gate Mine Permit Number: ACT/007/004  
Type of Mining Activity: Underground Surface Other  
County: Carbon  
Company Official(s): Rad Orell, Charles Sandberg  
State Official(s): Bill Malencik,  
Partial: X Complete:        Date of Last Inspection         
Weather Conditions: Clear and Sunny  
Acreage: Permitted        Disturbed        Regraded        Seeded        Bonded         
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:	( )	( )	( )	( )
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

DATE OF INSPECTION September 7, 1990

Page 2 of 2

On September 7, 1990, an aerial inspection of this site was conducted by the referenced State and Federal officials. No violations were observed.

Photographs (slides), were taken and are available at the Division of Oil, Gas and Mining, Salt Lake Office as well as the Office of Surface Mining, Albuquerque Field Office.

Copy of this Report:

Mailed/filed to: John Kathmann (OSM) Joe Helfrich (DOGM)

Filed to: Price Field Office

Inspectors Signature Jim J. Pralencik Date: September 11, 1990