



0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

DR7

NO. N 91-38-3-1

notice of violation

To the following Permittee or Operator:

Name AMAX Coal Co.

Mine Castle Gate Coal Surface Underground Other

County Carbon State UT Telephone _____

Mailing Address ONE River Front Place, 20 N.W. 1st STREET EVANSVILLE IND. 47708

State Permit No. ACT / 607 / 004

Ownership Category State Federal Fee Mixed

Date of inspection October 29, 19 91

Time of inspection 9:30 a.m. p.m. to 4:00 a.m. p.m.

Operator Name (other than Permittee) SAM

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling 10/31/91 Time of service/mailling 10:00 a.m. p.m.

Permittee/Operator representative _____ Title _____

Signature _____

Sharon K. Falvey Reclamation Hydrologist
Division of Oil, Gas & Mining representative Title

Sharon K. Falvey 38
Signature Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 91-38-3-1

Violation No. 1 of 1

Nature of violation

Improper placement and storage of Non Coal mine waste

Provisions of act, regulations or permit violated

R614-301-528.330

R614-301-528.331

Portion of operation to which notice applies

AREA surrounding culvert C-9 in Hardscrabble Canyon

Remedial action required (including any interim steps)

Remove waste materials berried around culvert C-9 at the inlet
Place Non coal waste in designated Storage Area
Re build berm surrounding inlet where disturbed.

Abatement time (including interim steps)

Five Working Days From Date of Mailing