



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 1 row: Representatives Present During the Inspection: OGM Jerriann Ernstsens Environmental Scientist II

Inspection Report

Table with 2 columns: Permit Number: C0070004, Inspection Type: PARTIAL, Inspection Date: Monday, June 12, 2006, Start Date/Time: 6/12/2006 11:00:00 AM, End Date/Time: 6/12/2006 2:00:00 PM, Last Inspection: Wednesday, May 10, 2006

Inspector: Jerriann Ernstsens, Environmental Scientist II

Weather: sunny, 90 degrees

InspectionID Report Number: 975

Accepted by: pgrubaug
7/7/2006

Permitee: CASTLE GATE HOLDING CO
Operator: CASTLE GATE HOLDING CO
Site: CASTLE GATE MINE
Address: PO BOX 30, HELPER UT 84526-0030
County: CARBON
Permit Type: PERMANENT COAL PROGRAM
Permit Status: RECLAIMED

Current Acreages

Table with 2 columns: Acreage, Category. Rows: 7,619.00 Total Permitted, 63.00 Total Disturbed, 29.20 Phase I, 18.20 Phase II, Phase III

Mineral Ownership

- Checked: Federal, State, County, Fee
Unchecked: Other

Types of Operations

- Checked: Underground, Surface, Loadout
Unchecked: Processing, Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the Castle Gate facilities. DOGM evaluated the Hardscrabble and Sowbelly reclaimed sites.

Inspector's Signature:

Date: Tuesday, June 13, 2006

Jerriann Ernstsens, Environmental Scientist II
Inspector ID Number: 52

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

|  | Evaluated                           | Not Applicable           | Comment                             | Enforcement              |
|--|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1. Permits, Change, Transfer, Renewal, Sale                      | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Signs and Markers   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Topsoil   | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 4.a Hydrologic Balance: Diversions                               | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments          | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 4.c Hydrologic Balance: Other Sediment Control Measures          | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 4.d Hydrologic Balance: Water Monitoring                         | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 4.e Hydrologic Balance: Effluent Limitations                     | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 5. Explosives  | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 6. Disposal of Excess Spoil, Fills, Benches                      | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 7. Coal Mine Waste, Refuse Piles, Impoundments                   | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 8. Noncoal Waste   | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 10. Slides and Other Damage                                      | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 11. Contemporaneous Reclamation                                  | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 12. Backfilling And Grading                                      | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 13. Revegetation   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 14. Subsidence Control   | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 15. Cessation of Operations                                      | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 16.a Roads: Construction, Maintenance, Surfacing                 | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 16.b Roads: Drainage Controls                                    | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 17. Other Transportation Facilities                              | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 18. Support Facilities, Utility Installations                    | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 19. AVS Check  | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 20. Air Quality Permit   | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 21. Bonding and Insurance  | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 22. Other  | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

**2. Signs and Markers**

Signs containing the required information were posted at access points to the reclaimed area at Sowbelly.

**4.a Hydrologic Balance: Diversions**

There was no visible flow or previous flow in the channels of either Sowbelly or Hardscrabble.

**9. Protection of Fish, Wildlife and Related Environmental Issues**

Observed one golden eagle in the shrubs at Hardscrabble.

**13. Revegetation**

No observable difference in vegetation since 2005 summer field visit. Same species and cover.

**16.a Roads: Construction, Maintenance, Surfacing**

The road leading to Hardscrabble gate is getting increasingly more rutted. One sink hole could be dangerous under certain conditions.