



State of Utah

Department of Natural Resources

MICHAEL R. STYLER  
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA  
Division Director

JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

| Representatives Present During the Inspection: |   |
|--|---|
| Company  | Dennis Ware Controller                    |
| OGM  | Steve Demczak Environmental Scientist III |

**Inspection Report**

|                  |                            |
|------------------|----------------------------|
| Permit Number:   | C0070004                   |
| Inspection Type: | PARTIAL                    |
| Inspection Date: | Monday, January 12, 2009   |
| Start Date/Time: | 1/12/2009 10:00:00 AM      |
| End Date/Time:   | 1/12/2009 12:00:00 PM      |
| Last Inspection: | Tuesday, December 16, 2008 |

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 37 deg, snow cover

InspectionID Report Number: 1881

Accepted by: jhelfric  
2/23/2009

Permittee: **CASTLE GATE HOLDING CO**  
 Operator: **CASTLE GATE HOLDING CO**  
 Site: **CASTLE GATE MINE**  
 Address: **PO BOX 30, HELPER UT 84526-0030**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **RECLAIMED**

**Current Acreages**

|          |                        |
|----------|------------------------|
| 7,619.00 | <b>Total Permitted</b> |
| 63.00    | <b>Total Disturbed</b> |
| 29.20    | <b>Phase I</b>         |
| 18.20    | <b>Phase II</b>        |
|          | <b>Phase III</b>       |

**Mineral Ownership**

- Federal
- State
- County
- Fee
- Other

**Types of Operations**

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

**Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:**

No violatios were issued.

The Permittee notified the Division that the required third quarter of 2008 surface water monitoring information for the Castle Gate Mine was in the DOGM EDI pipeline and was acceptable for uploading. All sites were monitored at the end of March and were reported as "no flow". The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit. There are no other "special" permit conditions. The field conditions in Sowbelly and Hardscrabble Canyons remain virtually unchanged, as does the condition of the reclaimed area for Adit #1.

Inspector's Signature:

Steve Demczak, Environmental Scientist III  
 Inspector ID Number: 39

Date Monday, January 12, 2009

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

|  | Evaluated                           | Not Applicable                      | Comment                             | Enforcement              |
|--|-------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Change, Transfer, Renewal, Sale                      | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Signs and Markers   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Topsoil   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.a Hydrologic Balance: Diversions                               | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments          | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 4.c Hydrologic Balance: Other Sediment Control Measures          | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.d Hydrologic Balance: Water Monitoring                         | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 4.e Hydrologic Balance: Effluent Limitations                     | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 5. Explosives  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 6. Disposal of Excess Spoil, Fills, Benches                      | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 7. Coal Mine Waste, Refuse Piles, Impoundments                   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 8. Noncoal Waste   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 10. Slides and Other Damage                                      | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 11. Contemporaneous Reclamation                                  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 12. Backfilling And Grading                                      | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 13. Revegetation   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 14. Subsidence Control   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 15. Cessation of Operations                                      | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 16.a Roads: Construction, Maintenance, Surfacing                 | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 16.b Roads: Drainage Controls                                    | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 17. Other Transportation Facilities                              | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 18. Support Facilities, Utility Installations                    | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 19. AVS Check  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 20. Air Quality Permit   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 21. Bonding and Insurance  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 22. Other  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |

**3. Topsoil**

All topsoil was used in reclamation.

**4.a Hydrologic Balance: Diversions**

Diversions were snow covered but would function during the snow melt.

**4.c Hydrologic Balance: Other Sediment Control Measures**

Adit #1 and the topsoil storage area are pocked to control sediment from leaving the sites.

**8. Noncoal Waste**

The two sites were clear of non-coal waste materials.

**10. Slides and Other Damage**

No slides were noticed at the sites.

**12. Backfilling And Grading**

All sites were backfilled and graded.

**16.a Roads: Construction, Maintenance, Surfacing**

Roads to the mines were snow covered.