

0007



## State of Utah

### Department of Natural Resources

MICHAEL R. STYLER  
*Executive Director*

### Division of Oil, Gas & Mining

JOHN R. BAZA  
*Division Director*

JON M. HUNTSMAN, JR.  
*Governor*

GARY R. HERBERT  
*Lieutenant Governor*

#### Representatives Present During the Inspection:

Company	Dennis Ware	Controller
OGM	Steve Demczak	Environmental Scientist III

# Inspection Report

Permit Number:	C0070004
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, April 14, 2009
Start Date/Time:	4/14/2009 10:00:00 AM
End Date/Time:	4/14/2009 12:00:00 PM
Last Inspection:	Thursday, April 23, 2009

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 70's

InspectionID Report Number: 2021

Accepted by: jhelfric  
6/4/2009

Permittee: **CASTLE GATE HOLDING CO**  
 Operator: **CASTLE GATE HOLDING CO**  
 Site: **CASTLE GATE MINE**  
 Address: **PO BOX 30, HELPER UT 84526-0030**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **RECLAIMED**

#### Current Acreages

7,619.00	<b>Total Permitted</b>
63.00	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

The Permittee notified the Division that the required fourth quarter of 2008 surface water monitoring information for the Castle Gate Mine was in the DOGM EDI pipeline and was acceptable for uploading. All sites were monitored at the end of March and were reported as "no flow". The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit. There are no other "special" permit conditions.

The field conditions in Sowbelly and Hardscrabble Canyons remain virtually unchanged, as does the condition of the reclaimed area for Adit #1.

Inspector's Signature:



Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date

Friday, May 01, 2009

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801  
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • [www.ogm.utah.gov](http://www.ogm.utah.gov)

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

The Mining and Reclamation Permit of DOGM will expire on December 24, 2009. Castle Gate is in Phase II in reclamation. There are two sub-stations and a small area (Adit #1) that are in Phase I.

**2. Signs and Markers**

Identification sign signs were checked and contain the correct information. The lock to Sowbelly was broken/busted off by vandals

**3. Topsoil**

All topsoil was used in reclamation.

**4.a Hydrologic Balance: Diversions**

The diversion was inspected and was functioning as designed this past winter.

**4.c Hydrologic Balance: Other Sediment Control Measures**

The reclaim site is plocked for sediment control.

**4.d Hydrologic Balance: Water Monitoring**

The permittee has been submitted the 4th quarter water data to the Division.

**6. Disposal of Excess Spoil, Fills, Benches**

There was no spoil since this was a underground coal mine.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile at Goose Island was reclaimed.

**8. Noncoal Waste**

The area was snow cover and no non-coal waste could be seen.

**9. Protection of Fish, Wildlife and Related Environmental Issues**

There were signs of deer grazing on the reclaim area.

**10. Slides and Other Damage**

No slides or damage was noticed during the inspection.

**12. Backfilling And Grading**

The sites are completely reclaimed. All backfilled material was used.

Permit Number: C0070004  
Inspection Type: COMPLETE  
Inspection Date: Tuesday, April 14, 2009

**13. Revegetation**

All sites are revegetated.

**16.a Roads: Construction, Maintenance, Surfacing**

The road to Crandall Canyon is in good condition.

**18. Support Facilities, Utility Installations**

There are no facilities at Castle Gate.

**21. Bonding and Insurance**

The bonding amount is \$490,000. The insurance policy will expire on Oct. 10, 2009.