



## State of Utah

Department of  
Natural ResourcesMICHAEL R. STYLER  
Executive DirectorDivision of  
Oil, Gas & MiningJOHN R. BAZA  
Division DirectorJON M. HUNTSMAN, JR.  
GovernorGARY R. HERBERT  
Lieutenant Governor

## Representatives Present During the Inspection:

Company	Dennis Ware	Controller
OGM	Steve Demczak	Environmental Scientist III

K
**Inspection Report**

Permit Number:	C0070004
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, October 13, 2009
Start Date/Time:	10/13/2009 2:00:00 PM
End Date/Time:	10/13/2009 4:00:00 PM
Last Inspection:	Tuesday, September 15, 2009

Inspector: Steve Demczak, Environmental Scientist IIIWeather: Sunny, 60'sInspectionID Report Number: 2168

Accepted by: jhelfric

10/29/2009

Permittee: **CASTLE GATE HOLDING CO**  
 Operator: **CASTLE GATE HOLDING CO**  
 Site: **CASTLE GATE MINE**  
 Address: **PO BOX 30, HELPER UT 84526-0030**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **RECLAIMED**

## Current Acreages

7,619.00	<b>Total Permitted</b>
62.42	<b>Total Disturbed</b>
62.42	<b>Phase I</b>
58.10	<b>Phase II</b>
	<b>Phase III</b>

## Mineral Ownership

- Federal  
 State  
 County  
 Fee  
 Other

## Types of Operations

- Underground  
 Surface  
 Loadout  
 Processing  
 Reprocessing

## Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violatios were issued.

The Permittee notified the Division that the required fourth quarter of 2008 surface water monitoring information for the Castle Gate Mine was in the DOGM EDI pipeline and was acceptable for uploading. All sites were monitored at the end of March and were reported as "no flow". The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit. There are no other "special" permit conditions.

The field conditions in Sowbelly and Hardscrabble Canyons remain virtually unchanged, as does the condition of the reclaimed area for Adit #1.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date Thursday, October 22, 2009

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**2. Signs and Markers**

Identification signs are at the gates to the property.

**3. Topsoil**

All topsoil was used in reclamation.

**4.a Hydrologic Balance: Diversions**

The diversions were spot-checked and would function during a storm event.

**4.c Hydrologic Balance: Other Sediment Control Measures**

The reclaim site is plocked for sediment control.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile at Goose Island was reclaimed.

**8. Noncoal Waste**

The site is clear of non-coal waste material.

**10. Slides and Other Damage**

No slides or damage was noticed during the inspection.

**12. Backfilling And Grading**

The sites are completely reclaimed. All backfilled material was used.

**18. Support Facilities, Utility Installations**

No support facilities are at these sites.