

From: Steve Demczak
To: Dennis Ware; Suzanne Steab
Date: 11/2/2010 8:36 AM
Subject: Oct Insp. Reports
Attachments: 20101102075347.pdf; 20101102075403.pdf; 20101102075418.pdf



The State of Utah
 Department of
 Natural Resources
 Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
 Executive Director

LOWELL P. BRAXTON
 Division Director

OLENE S. WALKER
 Governor

GAYLE F. McKEACHNIE
 Lieutenant Governor

Representatives Present During the Inspection:	
Company	Dennis Ware
OGM	Steve Demczak

Inspection Report

Permit Number:	C0070004
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, October 27, 2010
Start Date/Time:	10/27/2010 1:00:00 PM
End Date/Time:	10/27/2010 3:00:00 PM
Last Inspection:	Wednesday, September 22, 2010

Inspector: Steve Demczak

Weather: Sunny, 50's

InspectionID Report Number: 2541

Accepted by: jhelfric

11/2/2010

Permittee: **CASTLE GATE HOLDING CO**
 Operator: **CASTLE GATE HOLDING CO**
 Site: **CASTLE GATE MINE**
 Address: **PO BOX 30, HELPER UT 84526-0030**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **RECLAIMED**

Current Acreages

7,619.00	Total Permitted
62.42	Total Disturbed
62.42	Phase I
58.10	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violatios were issued.

The Permittee notified the Division that the required second quarter of 2010 surface water monitoring information for the Castle Gate Mine was in the DOGM EDI pipeline and was acceptable for uploading. The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit. There are no other "special" permit conditions.

The field conditions in Sowbelly and Hardscrabble Canyons remain virtually unchanged, as does the condition of the reclaimed area for Adit #1.

Inspector's Signature:

Steve Demczak,

Inspector ID Number: 39

Date Thursday, October 28, 2010

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
 Where ideas connect™

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

Castle Gate is in the Phase II stage of reclamation. There are two sub-stations and a small area (Adit #1) that are in Phase I.

2. Signs and Markers

Identification signs are at the gates to the property.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

Diversions were functioning as designed.

4.c Hydrologic Balance: Other Sediment Control Measures

The reclaimed site is pocked for sediment control.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile at Goose Island was reclaimed.

8. Noncoal Waste

The site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or damage was noticed during the inspection

12. Backfilling And Grading

The sites are completely reclaimed. All backfilled material was used.

13. Revegetation

All sites are revegetated.

14. Subsidence Control

A contractor was on site finding survey markers. These markers are to be removed prior to Phase III bond release.

16.a Roads: Construction, Maintenance, Surfacing

The road is graveled running through the property at Hardscrabble Canyon. There is no road at #5 Mine.

18. Support Facilities, Utility Installations

There are no facilities at Castle Gate and #5 Mine.

Permit Number: C0070004
Inspection Type: PARTIAL
Inspection Date: Wednesday, October 27, 2010

Inspection Continuation Sheet