

6-12-89
0012



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

SCJ
Joh

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: June 5, 1989
2:00pm - 4:00pm

Permittee and/or Operators Name: Utah Fuel Company
Business Address: P.O. Box 719, Helper, Utah 84527
Mine Name: Skyline Mine Permit Number: ACT/007/005
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): Keith Zobell
State Official(s): Lynn Kunzler & Brent Stettler
Partial: Complete: Date of Last Inspection: May 31, 1989
Weather Conditions: Partly cloudy and breezy.
Acreage: Permitted 4,834 Disturbed 75.9 Regraded Seeded Bonded 75.9
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	(X)
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005

DATE OF INSPECTION: 6/05/89

(Comments are Numbered to Correspond with Topics Listed Above)

11. Contemporaneous Revegetation. Disturbed areas associated with the construction of the South Fork Portal Breakout and the Forest Service Access Road have been seeded and mulched. Good germination was evident on those areas examined.


13. Revegetation. Shrub planting along the conveyor corridor is well underway. The operator indicated that the drip irrigation system had to be redesigned by the SCS but should be installed within the next couple of weeks. Even without the irrigation, shrubs planted this year were in good condition and doing well.

18. Support Facilities. Construction of the South Fork Portal Breakout was complete with the exception of constructing the fence to exclude animals and people from entering the portals. Mr. Zobell indicated that the fence materials have been ordered and that the fence construction will be complete by the end of the month.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, PFO

Given to: Joe Helfrich & Sue Linner - DOGM

Inspectors Signature and Number: 

#17 Date: 6/9/89