



gk DCA

0020

NO. N 92-37-4-1

notice of violation

To the following Permittee or Operator:

Name Utah Fuel Co. / Skyline Coal Co.

Mine Skyline Mine Surface Underground Other

County Carbon State UT Telephone (801) 637 7925

Mailing Address PO Box 719 Helper UT 84526

State Permit No. ACT 10071005

Ownership Category State Federal Fee Mixed

Date of inspection 5/20/92, 19__

Time of inspection 09:00 a.m. p.m. to 17:00 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

CERTIFIED MAIL PO 74 974 240

Date of service/mailling 5/22/92

Time of service/mailling 10:00 a.m. p.m.

GLEN A ZUMWALT
Permittee/Operator representative

VICE PRESIDENT and GENERAL MANAGER
Title

Signature _____

Division of Oil, Gas & Mining representative

Soils Reclamation Spec. / Inspector
Title

Orsula Burton
Signature

#37
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 92-37-4-1

Violation No. 1 of 1

Nature of violation

Failure to maintain sediment control in Area 17 of the Rail Road Load Out. Failure to prevent to the extent possible, additional contributions of sediment to stream flow or run off outside the permit area.

Provisions of act, regulations or permit violated

R-645-301-742

Portion of operation to which notice applies

Rail Road Load Out, BC 13 conveyor, Area 17 where coal fines in water are leaving the site through gullies underneath straw bales.

Remedial action required (including any interim steps)

Evaluate present installation of straw bales at Area 17 of Rail Road Load Out, with attention to sheet flow from underneath BC-13 conveyor. Replace present ineffective straw bales with fresh straw bales, ^{keyed in} ~~brushed~~, or silt fence material or both.

Abatement time (including interim steps)

15 days or June 8, 1992