



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: XX Complete: Exploration
Inspection Date/Time: October 13, 1994/08:00am-04:30pm
Date of Last Inspection: September 26, 1994

Mine Name: Skyline Mine County: Carbon Permit Number: ACT/007/005
Permittee and/or Operator's Name: Coastal States Energy/Utah Fuel
Business Address: P. O. Box 719, Helper, UT 84527
Type of Mining Activity: Underground XX Surface Prep. Plant Other
Officials(s): State: Stephen J. Demczak Company: Keith Zobell
Federal Official(s): Weather Conditions: Cool, 40's
Existing Acres: Permitted-7067.11 Disturbed-62.08 Regraded-Seeded- Bonded-65.38
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temp Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK; 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005

DATE OF INSPECTION: October 13, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

Reviewed the SAE and ASCA areas with the operators. The Skyline mine will be submitting updates to the mine plan requesting for additional SAE's and including additional designs for ASCAS.

4a. Sediment Ponds -

The sediment ponds were inspected with no hazardous conditions being noticed. Embankments were stable with the mine site pond discharging. With the new NPDES permit limits, Skyline has been in compliance.

4d. Water Monitoring -

Went to several water monitoring sites with operator and sampled surface and ground water sites for 3rd quarter water monitor requirements. Sites were designated on the ground for location for sampling. The sampling procedures were taken with a high degree of integrity and proficiency. No advice by inspector was given.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Coastal States Energy/Utah Fuel, Keith Zobell
Mailed to: Bernie Freeman (OSM) Given to: Joe Helfrich (DOGM)
Filed to: Price Field Office
Date: October 17, 1994

Inspector's Signature and Number:  #39
Stephen J. Demczak