

0013



Date: Sept 30, 1998

*Copy from
ACT/007/005
#6*

FAX COVER SHEET

To:

Daron Haddock

Company:

UDOGM

Fax No:

From:

Chris Hansen

Skyline Mines

P.O. Box 719

Helper, UT 84526

Fax Number: (435) 448-2632

Direct Dial: (435) 448- 2669

Pages:

3 (including this one)

Notes:

1998 Second Quarter Gob Pile
inspection & Quarterly Report. Hand
copy to follow in mail.

Confidentiality Notice: This message is intended only for the use of the individual or entity designated above, is confidential, and may contain information that is legally privileged or exempt from disclosure under applicable law. You are hereby notified that any dissemination, distribution, copying, or use of or reliance upon the information contained in and transmitted with this facsimile transmission by or to anyone other than the recipient designated above by the sender is *not authorized and strictly prohibited*. If you have received this communication in error, please immediately notify the sender by telephone and return it to the sender by U.S. Mail, or destroy it if authorization is granted by the sender.

If you have any trouble receiving the above specified pages, please call sender.

September 30, 1998


Coal Regulatory Program
Attn.: Mr. Daron Haddock
Permit Supervisor
Utah Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
Salt Lake City, Utah 84114-5801

RE: Second Quarter 1998 Waste Rock Pile report for Skyline Mines

Dear Mr. Haddock:

As required by the Skyline Mines Mining and Reclamation Plan, a copy of the 1998 second quarter certified inspection report for the Waste Rock Pile is being submitted. A total of approximately 19,104 tons of waste rock was placed at the site during the second quarter of 1998. Copies of the analyses results from samples obtained from the 19,104 tons will be submitted with the annual report. No exceedances of the Table 6 parameter limits occurred. If you have any questions regarding this report, please contact me at (435)448-2669.

Sincerely,



Chris D. Hansen
Environmental Coordinator
Canyon Fuel Company, LLC

attachments

24 June 1998

I, Carl Winters, certify that I inspected the Scofield Waste Rock Disposal site on 24 June 1998. The sedimentation ponds were dry. Drainage ditches have been constructed to route runoff from the pile to the sediment ponds at the upper end and base of the waste rock pile. The location of the topsoil stockpile has been change from the south side of the waste rock pile to the north side. Straw bales have been placed around the topsoil for sediment control. Waste rock was being added to the pile and was being compacted.

Surface cracks were noticed in the pile at the northeast corner near the road cut. However, no surface failures related to these cracks have occurred.



Carl W. Winters

Registered Professional Engineer

Utah Registration No. 22-157958-2202