


0035



Canyon Fuel Company, LLC  
Skyline Mines  
P.O. Box 719  
Helper, Utah 84526  
435/448-6463 Fax: 435/448-2632



14 January 1999

Coal Regulatory Program  
Attn: Mr. Daron Haddock  
Permit Supervisor  
Utah Division of Oil, Gas and Mining  
1594 West North Temple, Suite 1210  
Salt Lake City, UT 84114-5801

ACT/007/005 #6

RE: Fourth Quarter 1998 Waste Rock Pile Report for the Skyline Mines

Dear Mr. Haddock:

As required by the Skyline Mines Mining and Reclamation Plan, a copy of the certified inspection report for the Waste Rock Pile is being submitted. No waste rock was placed at the site during the fourth quarter of 1998. Also attached is a copy of the certified inspection report. If you have questions regarding this report, please contact me at (435) 448-2669.

Sincerely,


A handwritten signature in cursive script that reads 'Chris D. Hansen'.

Chris D. Hansen  
Environmental Coordinator  
Canyon Fuel Company, LLC

attachment

17 December 1998

I, J. Thomas Paluso, certify that I inspected the Scofield Waste Rock Disposal site on 17 December 1998. The sediment pond had a water elevation of 7860 feet. The stock pond had a water elevation of 7949 feet. Drainage ditches have been constructed to route runoff from the pile to the sediment ponds at the upper end and base of the waste rock pile. The location of the topsoil stock pile is on the north side. Straw bales have been placed around the topsoil for sediment control. No waste rock was being added to the pile during the time of the inspection.



*J. Thomas Paluso*  
J. Thomas Paluso  
Registered Professional Engineer  
Utah Registration No. 22-150267-2202

