

0013



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Michael O. Leavitt
Governor
Lowell P. Braxton
Division Director

Partial: XXX Complete: Exploration:
Inspection Date & Time: 7/26/99 / 10:00a.m.-1:30p.m.
Date of Last Inspection: 6/28/99

Mine Name: Skyline Mine County: Carbon Permit Number: ACT/007/005
Permittee and/or Operator's Name: Canyon Fuel Company
Business Address: P.O. Box 719, Helper, Utah 84526
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Gary Taylor
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm, 80's
Existing Acreage: Permitted- 7067.11 Disturbed- 62.08 Regraded- Seeded- Bonded- 65.38
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/005

DATE OF INSPECTION: 7/26/99

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT-

The permittee has submitted an amendment for installing two sediment sumps. Currently this amendment is being reviewed.

2. SIGNS AND MARKERS -

Identification signs meet the requirements of the R645 Coal Rules. The perimeter markers were spot-checked and are located around the perimeter of the disturbed areas.

3. TOPSOIL -

The topsoil piles were inspected with no signs of wind or water erosion. These piles are protected by vegetation, straw bales, or silt fences.

4A. DIVERSIONS -

The diversions were spot-checked and were found to comply with the requirements of the Mining and Reclamation Plan and the R645 Coal Rules performance standards.

4B. SEDIMENT PONDS -

The sediment pond at the mine site was discharging during the inspection. This was the only sediment pond that was discharging.

There were no signs of any hazardous conditions occurring to the sediment ponds during the inspection.

4C. OTHER SEDIMENT CONTROL MEASURES -

Skyline Mine uses straw bales, silt fences, gravel, and berms as its alternate sediment control measures. These areas were spot-inspected and complied with the R645 Coal Rules. Spot checks of these areas were made and no performance standards were violated.

7. REFUSE PILE -

The refuse pile was P.E. certified for first quarter on March 18, 1999. The report did not indicate any hazardous conditions.

The refuse pile had no signs of hazardous conditions during the field inspection.

INSPECTION REPORT
(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/005

DATE OF INSPECTION: 7/26/99

(Comments are Numbered to Correspond with Topics Listed Above)

8. NON-COAL WASTE -

The area was clear of non-coal waste material, except for a diversion ditch located at the upper mine site. Permittee was in the process of removing the material.


18. SUPPORT FACILITIES -

There were no additional support facilities constructed.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Chris Hansen (Canyon Fuel) Henry Austin (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: July 29, 1999

Inspector's Signature:  #39
Stephen J. Demczak