

Document Information Form

Mine Number: CI007/005

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: N/A

Explanation:

1998 ANNUAL REPORT REVIEW

cc:

File in: CI 007 , 005 , Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

007/005 #6
 CL: Steve

1998 Annual Report Review

Permittee: CANYON FUELS
 Mine Name: SKYLINE MINE
 Permit Number ACT/00/005
 Date Report Received 03/05/99
 Assigned Reviewers: S.J. DEMCZAK, Paul Baker, Mike Suflita

Instructions: The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the Mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine folder #6.

Assignments:
Inspectors: Review cover sheet, AVS legal/financial, Mine sequence map
Hydrologists: Review water monitoring data, Precipitation and climatological data, Non-coal waste
Biologists: Review vegetation/revegetation success monitoring, Raptor survey
Engineers: Review subsidence monitoring data, Annual impoundment certification, Annual overburden, spoils, refuse, floor, etc.

Section to review	Submitted		Findings
	Yes	No	
Cover sheet	<u>X</u>	___	complete and adequate
AVS; Legal/Financial Update	<u>x</u>	___	complete and adequate
Mine Sequence Map	<u>x</u>	___	complete and adequate
Water Monitoring Data	<u>X</u>	__	Adequate. Submitted previously as quarterly data.
Precipitation & Climatological Data	___	<u>X</u>	Not required.
Non-Coal Waste report	___	<u>X</u>	Not complete.
Subsidence monitoring data	<u>x</u>	___	complete and adequate
Annual Impoundment Certification	<u>x</u>	___	complete and adequate

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No. 0019 Date _____
 In C/ 007, 005, Internal
 For additional information

Annual Overburden, Spoil, Refuse, Floor, etc.	<u>X</u> ___	On file with DOGM
Vegetation data	___ <u>X</u>	
Revegetation Success monitoring	<u>X</u> ___	Report includes information about revegetation efforts on the conveyor bench. 5800 shrub and grass transplants were planted in areas 1, 2, and 3. The permittee's representative also indicated the area was again seeded.
Raptor survey	___ <u>X</u>	The permittee has this information on file. No nests were found in the area that was to be subsided in the coming year.
Other information	___ <u>X</u>	

O:\007005.SKY\ANNUALRP\REVIEW.FRM