

0035



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

*SWD
by
AD*

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Partial: _____ Complete: XXX Exploration: _____
Inspection Date & Time: 11/7/00 / 9:30am-2:30pm
Date of Last Inspection: 10/5/00

Mine Name: Skyline Mine County: Carbon Permit Number: C/007/005
Permittee and/or Operator's Name: Canyon Fuel Company
Business Address: HC 35 Box 380, Helper, Utah 84526
Type of Mining Activity: Underground XXX Surface _____ Prep. Plant _____ Other _____
Company Official(s): Chris Hansen, Gary Taylor
State Official(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Cool, five inches of snow
Existing Acreage: Permitted 7067.11 Disturbed 62.08 Regraded _____ Seeded _____
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/005

DATE OF INSPECTION: 11/7/00

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has submitted a Reclamation Agreement to the division for approval. At this time, there is a difference in permit acreage between the Division and the permittee. A meeting is schedule to resolve this issue. The Reclamation Agreement expired on January 1, 1999, but, a reclamation bond is still in place.

2. SIGNS AND MARKERS

The identification signs were inspected and complied with the R645 Coal Rules.

Several parameter markers were noticed during the inspection. It is becoming difficult to view the markers due to snow accumulations.

3. TOPSOIL

Topsoil piles at the mine site were snow covered with no signs of erosion. The topsoil pile at the refuse pile was inaccessible, therefore, no inspection could be made.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked and were functioning as designed in the Mining and Reclamation Plan.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The third quarter sediment pond's inspections were made with no hazardous conditions being reported. The mine site sediment pond was discharging during the inspection. Most of the discharging water was coming from the underground workings.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The silt fences at the site were functioning as designed. A section of silt fence was repaired as maintenance was needed from prior inspection.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Water monitoring was inspected for second quarter. The permittee is sending the information by electronic mailing. All monitoring sites, parameters, and holding times were met.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse pile was not accessible due to snow cover. There has been no changes to the refuse pile since the last inspection.

The refuse pile was inspected by a P.E. certified engineer for third quarter. No hazardous conditions were reported.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/005

DATE OF INSPECTION: 11/7/00

8. NONCOAL WASTE

The property was clear of non-coal waste material.

14. SUBSIDENCE CONTROL

The subsidence data for the year 2000 has been taken and the result will be in the Annual Report next March.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new support facilities have been added since the last inspection.

21. BONDING AND INSURANCE

The insurance report acord form was inspected. The insurance policy does comply with the requirements of the Utah R645 Coal Rules.

Inspector's Signature:


Stephen J. Demczak #39

Date: November 14, 2000

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM
Dan Meadors, Canyon Fuel
Chris Hansen, Canyon Fuel
Price Field office

O:\007005.SKY\Compliance\2000\c_1107.wpd