

## INSPECTION REPORT

Partial XXX Complete      Exploration       
 Inspection Date: 04/17/2003 Time: 9:00am-2:30pm  
 Date of Last Inspection: 03/21/2003

Mine Name: Skyline Mine County: Carbon Permit Number: C/007/005  
 Permittee and/or Operator's Name: Canyon Fuel Company, LLC.  
 Business Address: HC 35 Box 380, Helper, Utah 84526  
 Company Official(s): Chris Hansen  
 State Official(s): Stephen J. Demczak Federal Official(s): None  
 Weather Conditions: Sunny, 30's  
 Type of Mining Activity: Underground XXX Surface      Prep Plant      Other       
 Existing Acreage: Permitted 10,374 Disturbed 79.12 Regraded      Seeded       
 Status: Active

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 <sup>th</sup> Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**INSPECTION REPORT**  
(Continuation Sheet)

PERMIT NUMBER: C/007/005

DATE OF INSPECTION: 04/17/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

**1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE**

The permittee has two amendments submitted to the Division. These are the subsidence of Lawrence Reservoir and JC-3 Well. The Division is in the process of review. This information was found by reviewing the Division's CTS system.

**4A. HYDROLOGIC BALANCE: DIVERSIONS**

The diversions were spot-checked throughout the property. The permittee has cleaned out several diversions since the last inspection. The permittee was told by the inspector to clean out the diversion and sediment trap located at the rail loadout. The sediment trap and diversion has sediment starting to build-up. The permittee has committed in cleaning up the sediment in these areas.

**4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS**

I inspected the three sediment ponds within the Skyline disturbed area. There were no hazardous conditions noticed. The mine site pond was discharging during the inspection. The rail loadout will be discharging on and off throughout the spring. The refuse pile sediment will contain a small amount of water but most likely will not discharge.

**4D. HYDROLOGIC BALANCE: WATER MONITORING**

The permittee is in the process of taking second quarter water samples. This process will be completed by the end of the quarter.

**7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS**

The permittee has added additional refuse material to the pile since the last inspection. There were no signs of hazardous conditions to the refuse pile.

**8. NONCOAL WASTE**

The area was generally clear of non-coal waste material.

**18. SUPPORT FACILITIES/UTILITY INSTALLATIONS**

No new facilities have been added since the last inspection.

Inspector's Signature: \_\_\_\_\_ Date: April 30, 2003  
Stephen J. Demczak #39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM  
Dan Meadors, Canyon Fuel  
Chris Hansen, Canyon Fuel  
Price Field office

O:\007005.SKY\Compliance\2003\p\_0417.doc