



The State of Utah
 Department of
 Natural Resources
 Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GALE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection

OGM	Gregg Galecki	Reclamation Specialist II
Company	Chris D. Hansen	

Inspection Report

Permit Number:	C0070005
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, November 25, 2003
Start Date/Time:	11/25/2003 8:00:00 AM
End Date/Time:	11/25/2003 11:30:00 AM
Last Inspection:	Thursday, October 02, 2003

Inspector: Gregg Galecki, Reclamation Specialist II

Weather: Partly Cloudy, 25 deg. F., west wind

Accepted by: dhaddock
 11/26/2003

Permittee: **CANYON FUEL COMPANY LLC**
 Operator: **CANYON FUEL COMPANY LLC**
 Site: **SKYLINE MINE**
 Address: **HC 35 BOX 380, HELPER UT 84526**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

7,121.00	Total Permitted
83.92	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: _____

Date Wednesday, November 26, 2003

Gregg Galecki, Reclamation Specialist II

Inspector ID Number: 48

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
 - a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
 - b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

No new proposed changes or modifications of the MRP have been submitted to the Division since the last inspection.

2. Signs and Markers

Proper Mine identification was located at the entrance of the surface facility. The information was complete and complied with R645 Coal regulations.

4.a Hydrologic Balance: Diversions

An inspection of the diversions within the surface facilities was conducted. No maintenance issues were observed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Ponds were inspected and observed to be functioning as designed. Ponds were inspected on 16Sept03 for the third quarter.

4.c Hydrologic Balance: Other Sediment Control Measures

Drainage at the entrance of the Loadout facility was improved with cleaning and replacement of new strawbales since the last inspection.

4.d Hydrologic Balance: Water Monitoring

Second quarter water monitoring was submitted prior to the October 15, 2003 extension. Third quarter water monitoring has been conducted and is in the pipeline. Only minimal water monitoring is conducted in the fourth quarter. All required water monitoring is being provided to the Division.

4.e Hydrologic Balance: Effluent Limitations

Hard copies of the DMRs were available through September 2003. Limits on UPDES permit UT0023540 were modified this year to reflect a TDS 500 mg/l concentration limit. If exceeded, a 7.2 ton/day limit goes into effect.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was safety inspected and PE certified on September 15, 2003, as having no hazardous conditions.

8. Noncoal Waste

The mine site was clear of non-coal waste material.

11. Contemporaneous Reclamation

Reclamation of the South Fork Portals was completed since the last inspection. Snow cover prohibits adequate inspection of the site at this time.

14. Subsidence Control

The subsidence survey was flown in September-October 2003. Results will be included in the 2003 Annual Report.

16.b Roads: Drainage Controls

Roads through out the surface facility were inspected and found to be functioning as designed.

19. AVS Check

An AVS check was conducted during the May 2003 Complete Inspection.

20. Air Quality Permit

A current Air Quality Permit was on site. Permit DAQE-AN0092007-03 was last modified and re-issued on 24Jun03.