

99A ★ EQUIPMENT DESCRIPTION:
SINGLE SHIELD, RAMS AND HOSES REMOVED.
NO REMAINING FLUIDS. ABANDONED 6/95.

99B ★ EQUIPMENT DESCRIPTION:
CONVEYOR BELT TAIL, STEEL AND RUBBER
ONLY. NO REMAINING FLUIDS. ABANDONED
12/98.


99C ★ EQUIPMENT DESCRIPTION:
LONGWALL EMULSION TANK, 3000 GAL.
CAPACITY. NO REMAINING FLUIDS.
ABANDONED 12/98.

99D ★ EQUIPMENT DESCRIPTION:
FOUR LONGWALL SHIELDS, USEABLE PARTS
REMOVED. EMULSION REMOVED. NO
REMAINING FLUIDS. ABANDONED 12/98.

01E ★ EQUIPMENT DESCRIPTION:
LONGWALL FACE CONVEYOR. 160 PAN
SECTIONS. NO FLUIDS OF HOSES REMAIN.
STEEL ONLY. ABANDONED 4/01

04F ★ EQUIPMENT DESCRIPTION:
(POTENTIAL) 121 EACH DOWTY AND K-B ROOF
SUPPORTS (SHIELDS). LONGWALL FACE
CONVEYOR COMPLETE WITH LINE PANS,
SPECIAL PANS, HEADGATE AND TAILGATE
DRIVES AND STAGELoader. JOY
DOUBLE-ENDED RANGING DRUM LONGWALL
SHEARING MACHINE.

04G ★ EQUIPMENT DESCRIPTION:
APPROXIMATELY 82 K-B ROOF SUPPORT
SHIELDS BETWEEN XCUTS 22 AND 37, 6L B
PANEL. NO FLUIDS REMAIN. STEEL ONLY.
ABANDONED 3/04



THIS MAP IS CORRECT TO THE BEST OF MY KNOWLEDGE AND
IS CERTIFIED TO BE AN ACCURATE REPRESENTATION OF
CURRENT ABANDONED UNDERGROUND
SEAL:

PROFESSIONAL ENGINEER:
REGISTRATION NO.:

REVISIONS	
DATE:	BY:
6/10/03	DEJ
3/04/04	CDH

MINE 3 LEVELS 2 & 3
ABANDONED MINING EQUIPMENT LOCATIONS

Canyon Fuel Company, LLC
Skyline Mines

P.O. BOX 700 BUREAU, UTAH 84302
435-440-5443
DATE: 6/09/03 CK BY: C. HANSEN REVISION:
SCALE: 1"=500' DR. BY: S. CURTIS
DWG. NO.: 2.3.6-3

RECEIVED
MAR 05 2004
DIV. OF OIL, GAS & MINING

