



The State of Utah
 Department of
 Natural Resources

Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:		
Company	Gregg Galecki	Environmental Scientist III
Company	Steve Demczak	Environmental Scientist III

Inspection Report

Permit Number:	C0070005
Inspection Type:	COMPLETE
Inspection Date:	Monday, February 14, 2005
Start Date/Time:	2/14/2005 10:00:00 AM
End Date/Time:	2/14/2005 2:00:00 PM
Last Inspection:	Wednesday, January 26, 2005

Inspector: Steve Demczak, Environmental Scientist III

Weather: Snow Covered, Partly Cloudy

InspectionID Report Number: 546

Accepted by: pgrubaug
 3/3/2005

Permittee: **CANYON FUEL COMPANY LLC**
 Operator: **CANYON FUEL COMPANY LLC**
 Site: **SKYLINE MINE**
 Address: **HC 35 BOX 380, HELPER UT 84526**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

10,374.00	Total Permitted
79.12	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions:

- 1) Submit Water Monitoring data in electronic format to the Division.
- 2) Canyon Fuel Co. must submit all existing studies and data for the update of the PHC as a result of the mine inflows.
- 3) Canyon Fuel Co. must submit cumulative monthly flow data for discharges into Electric Lake and Eccles Creek.
- 4) Canyon Fuel Co. must have a qualified person compile and analyze past macroinvertebrate studies on Eccles Creek into one report.
- 5) Canyon Fuel Co. must initiate an update to and further evaluation of the Hydrologic and Channel-Stability Evaluation of Eccles and Mud Creek.

The permittee is meeting these permit conditions.

Permit Renewal was April 30, 2002, and expires on April 30, 2007.

Inspector's Signature

Date Tuesday, March 01, 2005

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The Mining and Reclamation Permit will expire on April 30, 2007.

2. Signs and Markers

The identifications signs were inspected and complied with the R645 Coal Rules.

3. Topsoil

Topsoil piles were covered with 3 to 4 feet of snow.

4.a Hydrologic Balance: Diversions

The diversions were spot checked and open for water flow. Several of the diversions were recently cleaned out.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The mine site and loadout sediment ponds were inspected with no hazardous conditions noticed during the inspection. The permittee inspected the sediment ponds for the fourth quarter on December 29, 2004. No hazardous conditions were reported.

4.c Hydrologic Balance: Other Sediment Control Measures

Majority of the silt fences were snow covered.

4.d Hydrologic Balance: Water Monitoring

The permittee is in the process of entering and receiving information for 4th quarter water samples.

4.e Hydrologic Balance: Effluent Limitations

The UPDES permit is effective on December 1, 2004 and expires on November 20, 2009. The permit number is UT0023540.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inaccessible due to snow cover.

8. Noncoal Waste

The area was clear of non-coal waste material.

15. Cessation of Operations

The mine is in a limited production status. The mine is operating one continuous miner section.

Permit Number: C0070005
Inspection Type: COMPLETE
Inspection Date: Monday, February 14, 2005

18. Support Facilities, Utility Installations

No new support facilities have been added since the last inspection.

22. Other

The SPCC Plan is in the process of being updated.