

Pre-SMCRA, Pre-1977 Mining
Streams
Major Faults
Dikes
Ground Monit.
Surface Water Monit. Site
UPDES Monit. Site

Cumulative Hydrologic Impact Assessment
Mud Creek - Upper Huntington Creek Basin

Figure 3b
White Oak and Blazon Mines
Mining and Geology

File--n:\gis\coal\ciamaps\mudcreek\map-mining2.gra

Compiled by: Dan Smith Date: October 24, 2005

State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining

N

0 1/4 1/2 1 mi
0 1000 2000 5000 ft
0 1/4 1/2 1 k
Scale 1:32142 (verify scale)



Location Map