



GARY R. HERBERT

Governor

GREG BELL

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

8

Inspection Report

Permit Number:	C0070005
Inspection Type:	COMPLETE OVERSITE
Inspection Date:	Wednesday, October 20, 2010
Start Date/Time:	10/20/2010 10:00:00 AM
End Date/Time:	10/20/2010 4:30:00 PM
Last Inspection:	Thursday, September 09, 2010

Representatives Present During the Inspection:	
Company	Gregg Galecki
OSM	Christine Belka
OGM	Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Clear, Temp. 57 deg. F.

InspectionID Report Number: 2534

Accepted by: jhelfric

11/2/2010

Permittee: **CANYON FUEL COMPANY**

Operator: **CANYON FUEL COMPANY**

Site: **SKYLINE MINE**

Address: **HC 35 BOX 380, HELPER UT 84526**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

11,064.00	Total Permitted
121.97	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The following permit conditions have been met or are being met:

- 1) Water Monitoring data is being submitted in an electronic format to the Division.
- 2) Canyon Fuel Co. must submit cumulative monthly flow data for discharges into Electric Lake and Eccles Creek. This condition is being met.


Inspector's Signature: _____

Date Wednesday, October 20, 2010

Karl Houskeeper,

Inspector ID Number: 49

Note: This Inspection Report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining. telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/007/005 was issued effective 04/30/2007 and expires 04/30/2012.

-Certificate of Insurance policy number GL093-61-11, issued 07/31/2010 and terminates 07/31/2011.

-UPDES permit # UT0023540 effective 12/01/2009 and expires @ midnight 11/30/2014.

-Air Quality permit DAQE-AN0092007-03, issued June 24, 2003.

-SPCC Plan dated 12/2//09. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E. on 12/30/09.

2. Signs and Markers

The Mine ID signs are at the point of public access to the permit area and contain the required information. All other signs and markers are in accordance with the coal rules.

A mine identification sign, topsoil sign and stream buffer zone signs are needed at the Winter Quarters facility that is under construction. Items were discussed with Gregg Galecki during the inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds at the mine site were inspected on September 30, 2010 for third quarter of 2010.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the discharge monitoring reports for September 2010. No exceeded parameters were identified on the reports.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected on September 30, 2010 for third quarter of 2010.

18. Support Facilities, Utility Installations

Observed the construction activities at the Winter Quarters Fan area. The topsoil pile has a silt fence around the base of the pile. The construction of the hilfiker hall was taking place in compacted lifts. A mine identification, topsoil and stream buffer signs are needed.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-AN0092007-03 was issued on June 24, 2003. The permit remains effective.

Permit Number: C0070005
Inspection Type: COMPLETE OVERSITE
Inspection Date: Wednesday, October 20, 2010

21. Bonding and Insurance

The current bond is \$5,137,000.00 as of September 19, 2006. The previous bond amount was \$5,076,000.00. The bond from St. Paul Fire and Marine Insurance Company was released on February 4, 2009 and Bond #SUR0000311 issued by Rockwood Casualty Insurance Company was accepted as a replacement in the same amount.