

Outgoing
00070005
K

Suzanne Steab - July 2011 Inspection Report

From: Karl Houskeeper
To: GGalecki@archcoal.com
Date: 7/28/2011 1:41 PM
Subject: July 2011 Inspection Report
CC: ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov
Attachments: Skyline July 2011.pdf

Gregg,

Attached is the July 2011 inspection report for Skyline.

Thanks,
Karl



GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070005
Inspection Type:	COMPLETE
Inspection Date:	Monday, July 18, 2011
Start Date/Time:	7/18/2011 8:30:00 AM
End Date/Time:	7/18/2011 2:30:00 PM
Last Inspection:	Thursday, June 09, 2011

Inspector: Karl Houskeeper

Weather: Partly Cloudy, Temp. 72 Deg. F.

InspectionID Report Number: 2802

Accepted by: jheffric

7/28/2011

Representatives Present During the Inspection:

Company	Gregg Galecki
OGM	Karl Houskeeper

Permittee: **CANYON FUEL COMPANY**
Operator: **CANYON FUEL COMPANY**
Site: **SKYLINE MINE**
Address: **HC 35 BOX 380, HELPER UT 84526**
County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

121.97	Total Permitted
121.97	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The following permit conditions have been met or are being met:

- 1) Water Monitoring data is being submitted in an electronic format to the Division.
- 2) Canyon Fuel Co. must submit cumulative monthly flow data for discharges into Electric Lake and Eccles Creek. This condition is being met.

Inspector's Signature: _____

Date

Monday, July 18, 2011

Karl Houskeeper,

Inspector ID Number: 49

Note: This inspection report does not constitute an approval or compliance with the regulatory program of the Division of Oil, Gas and Mining.
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



Permit Number: C0070005
 Inspection Type: COMPLETE
 Inspection Date: Monday, July 18, 2011

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS, PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/007/005 was issued effective 04/30/2007 and expires 04/30/2012.

-Certificate of Insurance policy number GL093-61-11, issued 07/31/2010 and terminates 07/31/2011.

-UPDES permit # UT0023540 effective 12/01/2009 and expires @ midnight 11/30/2014.

-Air Quality permit DAQE-AN0092007-03, issued June 24, 2003.

-SPCC Plan dated 12/2//09. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E. on 12/30/09.

2. Signs and Markers

The Mine ID signs are at the point of public access to the permit area and contain the required information. All other signs and markers are in accordance with the coal rules.

A mine identification sign is needed at the Winter Quarters facility. Sign is available but needs to be placed at site (at point of public access into the permit area). Disturbed area markers need to be placed at the Winter Quarter s Facility.

4.a Hydrologic Balance: Diversions

Culvert inlet to the right side of the entrance into the main parking area at the main facilities is 50% covered and needs to be cleaned.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment ponds at the main mine site, rail load out and winter quarters area were inspected on June 14, 2011. The waste rock sediment pond and Winter Quarters sediment pond were inspected on June 7, 2011. These inspections constitute the second quarter of 2011 pond inspections.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the discharge monitoring reports for May and June 2011. No exceeded parameters were identified on the reports.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected on June 27, 2011 for the second quarter of 2011.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-AN0092007-03 was issued on June 24, 2003. The permit remains effective.

Permit Number: C0070005
Inspection Type: COMPLETE
Inspection Date: Monday, July 18, 2011

Inspection Continuation Sheet

Page 4 of 4

21. Bonding and Insurance

The current bond is \$5,137,000.00 as of September 19, 2006. The previous bond amount was \$5,076,000.00. The bond from St. Paul Fire and Marine Insurance Company was released on February 4, 2009 and Bond #SUR0000311 issued by Rockwood Casualty Insurance Company was accepted as a replacement in the same amount.