



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

| | |
|------------------|-------------------------|
| Permit Number: | C0070005 |
| Inspection Type: | COMPLETE |
| Inspection Date: | Thursday, June 07, 2012 |
| Start Date/Time: | 6/7/2012 8:30:00 AM |
| End Date/Time: | 6/7/2012 1:00:00 PM |
| Last Inspection: | Thursday, May 03, 2012 |

Inspector: Karl Houskeeper

Weather: Clear Skies, Temp. 60 Deg. F.

InspectionID Report Number: 3124

Accepted by: jhelfric

6/20/2012

Permitee: **CANYON FUEL COMPANY**
 Operator: **CANYON FUEL COMPANY**
 Site: **SKYLINE MINE**
 Address: **HC 35 BOX 380, HELPER UT 84526**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

| | |
|--------|------------------------|
| 121.97 | Total Permitted |
| 121.97 | Total Disturbed |
| | Phase I |
| | Phase II |
| | Phase III |

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The following permit conditions have been met or are being met:

- 1) Water Monitoring data is being submitted in an electronic format to the Division.
- 2) Canyon Fuel Co. must submit cumulative monthly flow data for discharges into Electric Lake and Eccles Creek. This condition is being met.

Karl R. Houskeeper

Inspector's Signature:

Date Thursday, June 07, 2012

Karl Houskeeper,
Inspector ID Number: 49



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | Evaluated | Not Applicable | Comment | Enforcement |
|--|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1. Permits, Change, Transfer, Renewal, Sale | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Signs and Markers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Topsoil | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.a Hydrologic Balance: Diversions | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.c Hydrologic Balance: Other Sediment Control Measures | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.d Hydrologic Balance: Water Monitoring | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.e Hydrologic Balance: Effluent Limitations | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Explosives | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Disposal of Excess Spoil, Fills, Benches | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Coal Mine Waste, Refuse Piles, Impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 8. Noncoal Waste | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Slides and Other Damage | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. Contemporaneous Reclamation | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Backfilling And Grading | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. Revegetation | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 14. Subsidence Control | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. Cessation of Operations | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.a Roads: Construction, Maintenance, Surfacing | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.b Roads: Drainage Controls | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 17. Other Transportation Facilities | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. Support Facilities, Utility Installations | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS Check | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20. Air Quality Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 21. Bonding and Insurance | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 22. Other | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/007/005 was issued effective 04/30/20012 and expires 04/30/2017.

-Certificate of Insurance policy number GL093-61-11, issued 07/31/2011 and terminates 07/31/2012.

-UPDES permit # UT0023540 effective 12/01/2009 and expires @ midnight 11/30/2014.

-Air Quality permit DAQE-AN0092007-03, issued June 24, 2003.

-SPCC Plan dated 12/2//09. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E. on 12/30/09.

2. Signs and Markers

All mine identification signs observed at entrances into the permit area at varied locations were uniform. The signs contained the required information.

4.a Hydrologic Balance: Diversions

Several diversions throughout the site have been re-graded and defined.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The main sediment pond is currently being cleaned.

The first quarter 2012 sediment pond inspections for the main sediment pond, load-out sediment pond, waster rock sediment pond and winter quarters sediment pond were done on March 6, 2012 and compiled into a report dated April 12, 2012.

4.e Hydrologic Balance: Effluent Limitations

The discharge monitoring reports for April 2012 were reviewed as part of the complete inspection. No problems were observed.

7. Coal Mine Waste, Refuse Piles, Impoundments

The waste rock site (refuse pile), was inspected during the first quarter of 2012 on March 28, 2012. The inspection is documented on a report dated April 12, 2012, which is P.E. signed, dated and stamped by a Utah P.E.

8. Noncoal Waste

Several items of noncoal waste were observed on the road way and in the diversion near the explosive storage area. These items need to be collected and placed in the approved noncoal waste storage area.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-AN0092007-03 was issued on June 24, 2003. The permit remains effective.

Permit Number: C0070005
Inspection Type: COMPLETE
Inspection Date: Thursday, June 07, 2012

21. Bonding and Insurance

The current bond is \$5,137,000.00 as of September 19, 2006. The previous bond amount was \$5,076,000.00. The bond from St. Paul Fire and Marine Insurance Company was released on February 4, 2009 and Bond #SUR0000311 issued by Rockwood Casualty Insurance Company was accepted as a replacement in the same amount.