



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 MICHAEL R. STYLER
Executive Director
Division of Oil, Gas and Mining
 JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070005
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, May 12, 2015
Start Date/Time:	5/12/2015 9:00:00 AM
End Date/Time:	5/12/2015 2:00:00 PM
Last Inspection:	Wednesday, April 22, 2015

Representatives Present During the Inspection:	
Company	Gregg Galecki
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Cloudy, 40's

InspectionID Report Number: 4198

Accepted by: JHELFRIC
 6/11/2015

Permitee: **CANYON FUEL COMPANY**
 Operator: **CANYON FUEL COMPANY**
 Site: **SKYLINE MINE**
 Address: **HC 35 BOX 380, HELPER UT 84526**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

10,611.41	Total Permitted
122.31	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The mine site was active.
 No trucks were noticed at the truck load out.

S t e p h e n J . D e m c z a k

Inspector's Signature:

Steve Demczak,
 Inspector ID Number: 39

Date Tuesday, May 26, 2015



Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

DOGMA Permit – Expires on April 30, 2017, and the permit is signed by both parties.
Air quality – DAQE-AN0092007-03
UPDES Permit- Expires on April 30, 2020

2. Signs and Markers

The identification sign contained the same information as noted in Chapter 1 in the Mining and Reclamation Plan. The Identification sign meets the requirements in the R645 Coal Rules.

3. Topsoil

The topsoil piles were inspected with no signs or wind or water erosion. These piles had vegetative cover with grasses and small shrubs.

4.a Hydrologic Balance: Diversions

The diversions were open and functioning as designed. Several diversions were recently cleaned out and graded since the last inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected for the first quarter on March 24, 2015. There were no hazardous conditions reported. I inspected these sediment ponds and they appeared to be stable. The mine water was discharging during the inspection. This is normal and always discharges mine water into Eccles Creek. The discharged water is sampled following the UPDES Permit requirements.

4.d Hydrologic Balance: Water Monitoring

The water data for the first quarter of 2015 has been submitted to the Division's database in Salt Lake City for review by the assigned hydrologist.

4.e Hydrologic Balance: Effluent Limitations

The permittee was in compliance with the DMR's for the first quarter of 2015.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected on March 30, 2015 with no hazardous conditions reported. I inspected the refuse pile and it appears to be stable. No mining related activities were occurring on the refuse pile during the inspection.

8. Noncoal Waste

The site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or other damage were noticed during the inspection.

14. Subsidence Control

The subsidence survey is conducted yearly and is submitted in the annual report.

16.a Roads: Construction, Maintenance, Surfacing

Several roads within the disturbed area that are not asphalted were recently graded.

18. Support Facilities, Utility Installations

No new support facilities were constructed since the last inspection.

21. Bonding and Insurance

The current bond is \$5,137,000.00 as of September 19, 2006. The previous bond amount was \$5,076,000.00. The bond from St. Paul Fire and Marine Insurance Company was released on February 4, 2009 and Bond #SUR0000311 issued by Rockwood Casualty Insurance Company was accepted as a replacement in the same amount. The insurance policy will expire on February 1, 2016. The policy meets the minimum requirements of the R645 Coal Rules.



