



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 MICHAEL R. STYLER
Executive Director
 Division of Oil, Gas and Mining
 JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070005
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, October 11, 2017
Start Date/Time:	10/11/2017 9:00:00 AM
End Date/Time:	10/11/2017 12:30:00 PM
Last Inspection:	Wednesday, September 13, 2017

Representatives Present During the Inspection:	
Company	Gregg Galecki
OGM	Steve Demczak

Inspector: Steve Demczak
 Weather: Cloudy, 60's, Dry Conditions
 InspectionID Report Number: 5986
 Accepted by: DHADDOCK
 10/27/2017

Permittee: **CANYON FUEL COMPANY**
 Operator: **CANYON FUEL COMPANY**
 Site: **SKYLINE MINE**
 Address: **HC 35 BOX 380, HELPER UT 84526**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages		Mineral Ownership	Types of Operations
10,958.09	Total Permitted	<input checked="" type="checkbox"/> Federal	<input checked="" type="checkbox"/> Underground
139.81	Total Disturbed	<input checked="" type="checkbox"/> State	<input type="checkbox"/> Surface
	Phase I	<input type="checkbox"/> County	<input type="checkbox"/> Loadout
	Phase II	<input checked="" type="checkbox"/> Fee	<input type="checkbox"/> Processing
	Phase III	<input type="checkbox"/> Other	<input type="checkbox"/> Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The mine was active.
 The permittee needs to submit photos of the two minor exploration sites when completed.

Stephen J. Demczak

Inspector's Signature:

Date Tuesday, October 24, 2017

Steve Demczak,
 Inspector ID Number: 39



Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The Division is waiting on Skyline to respond on PMLU & bond release. The response is schedule to be received by the Division by October 31, 2017.

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm. See Photo

4.a Hydrologic Balance: Diversions

I inspected diversions and culverts throughout the property. They were open and would function as designed during a storm event. The structures were recently re-graded and cleaned out of sediment. See photos

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment pond. It contained some water. The embankments appear to be stable. Inlets and outlets would function as designed. I did not see any hazardous conditions to this structure.

8. Noncoal Waste

The property was clear of non-coal waste materials such as oil, trash and grease cans.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection. The mine site appears to be stable.

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem.

16.b Roads: Drainage Controls

I inspected the road diversions and culverts throughout the property. They were functioning as designed. See Photos

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.







CANYON FUEL CO., LLC
SKYLINE MINES

225 No. 5th St. - Suite 900
Grand Junction, CO 81501
Phone 970-263-5130

MSHA:

Skyline No. 1 42-01435
Skyline No. 3 42-01566
ACT: C/007/005





TOP SOIL



ATTENTION
PARK BRAKE TEST LOCATION
STOP HERE AND TEST
YOUR PARK BRAKE















SPEED
LIMIT
15

15 MPH

