



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070005
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, October 2, 2019
Start Date/Time:	10/2/2019 9:00:00 AM
End Date/Time:	10/2/2019 3:00:00 PM
Last Inspection:	Tuesday, September 10, 2019

Representatives Present During the Inspection:	
Company	Gregg Galecki
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Sunny, 50's, Dry Conditions

InspectionID Report Number: 6541

Accepted by: SCHRISTE

10/30/2019

Permittee: **CANYON FUEL COMPANY**
 Operator: **CANYON FUEL COMPANY**
 Site: **SKYLINE MINE**
 Address: **HC 35 BOX 380, HELPER UT 84526**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

10,958.09	Total Permitted
139.45	Total Disturbed
0.36	Phase I
0.36	Phase II
0.36	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The mine was active mining and shipping of coal. The permittee has completely installed a new rubber conveyor belt from the mine to the loadout. This should reduce the chances of coal spills.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date Tuesday, October 22, 2019



Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining. telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

There is one amendment the Division is reviewing. It is the Skyline Seismic Station Installation. The review is schedule to be complete by October 23, 2019.

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm.

4.a Hydrologic Balance: Diversions

I inspected diversions and culverts throughout the property. They were open and would function as design in a storm event. See Photos.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds throughout the property. They contained some water but were not discharging. The mine and loadout sediment ponds could discharge in the near future depending on weather conditions. The embankments appear to be stable. Inlets and outlets would function as design. I did not see any hazardous conditions to these structures.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences, waddles, and straw bales were inspected and comply with the requirement of the R645 Coal Rules.

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile is active.

8. Noncoal Waste

The property was clear of non-coal waste materials such as oil, trash and grease cans.

10. Slides and Other Damage

No slides or other damage was notice during the inspection. The mine site appears to be stable.

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem.

16.b Roads: Drainage Controls

I inspected the road diversions and culverts throughout the property. They were functioning as design. See Photos

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.

19. AVS check

AVS checks are made in Salt Lake City.



CANYON FUEL CO., L.L.C.
SKYLINE MINES

9815 S Monroe St Ste 203
Sandy, Utah 84070

MSHA:

Skyline No. 1 42-01435

Skyline No. 3 42-01566

ACT: C/007/005













