



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070005
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, September 15, 2020
Start Date/Time:	9/15/2020 8:30:00 AM
End Date/Time:	9/15/2020 3:30:00 PM
Last Inspection:	Thursday, August 6, 2020

Representatives Present During the Inspection:	
Company	Gregg Galecki
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Partly cloudy, 80's, Dry Conditions

InspectionID Report Number: 6779

Accepted by: SCHRISTE

9/30/2020

Permittee: **CANYON FUEL COMPANY**
 Operator: **CANYON FUEL COMPANY**
 Site: **SKYLINE MINE**
 Address: **HC 35 BOX 380, HELPER UT 84526**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

10,958.09	Total Permitted
146.74	Total Disturbed
0.36	Phase I
0.36	Phase II
0.36	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The mine was in full operation, mining and shipping coal. The permittee and I took water sample at Winter Quarters. The Permittee took a field sample for total iron. The result was .77mg/l. The Permittee lab sample was .89 mg/l.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date Tuesday, September 29, 2020



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

There are no pending amendments with the Division at this time.

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm. See Photo

4.a Hydrologic Balance: Diversions

I inspected diversions and culverts throughout the property. They were open and would function during in a storm event. The diversions have not received little water this summer. See Photos.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond #001 (Mine pond) was clean out since the last inspection. The clean out material was taken to the refuse pile. The pond 002 contains water but was not discharging, and pond 003 and 004 were dry. Winter quarter pond 004 culvert outlet was discharging and the permittee and I took a water sample for total iron. The result from the permittee lab was 0.89 mg/l.

4.c Hydrologic Balance: Other Sediment Control Measures

I inspected several catch basin and they would function during a storm event.

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile is active. The permittee has place sediment pond clean out material to the refuse pile.

8. Noncoal Waste

The property was clear of non-coal waste materials such as oil, trash and grease cans.

10. Slides and Other Damage

No slides or other damage was notice during the inspection. The mine site and loadout appear to be stable.

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem. The roads were wet and had been recently water.

16.b Roads: Drainage Controls

Road diversions and culverts were open. These structures would function during a rain storm.

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.

ATTACHMENT A – Skyline




PHOTO 1
Identification Sign



PHOTO 2
Sediment Pond 001



PHOTO 3
Outlet of 004
Winter Quarters



PHOTO 4
Refuse Pile