



0041

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 86-8-1-1

To the following Permittee or Operator:

Name Plateau Mining Company

Mine Starpoint #2 Mine Surface Underground Other

County Carbon State Utah Telephone 637 2875

Mailing Address PO Drawer PMC Price UT 84501

State Permit No. Act 1007/006

Ownership Category State Federal Fee Mixed

Date of inspection 1/9/86, 19 86

Time of inspection 930 a.m. p.m. to 400 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing 1/9/86

Time of service/ mailing 400 a.m. p.m.

Robert G Lauman
Permittee/Operator representative

Chief Engineer
Title

Robert G Lauman 1-9-86
Signature

Mining Field Specialist
Title

Thomas W Wright
Division of Oil, Gas & Mining representative

8
Identification Number

Thomas W Wright
Signature

SEE REVERSE SIDE

WHITE-DOGMI YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

803



NOTICE OF VIOLATION NO. N86-8-1-1

Violation No. 1 of 1

Nature of violation

Failure to maintain appropriate sediment control measures using the best technology available

Provisions of act, regulations or permit violated

UMC 817.45 (iii)(c)

UMC 817.41 (a)

UCA 40-10-17 (2)(j)(ii)(A)

Portion of operation to which notice applies

#9 ditch just above inlet to bypass culvert at upper rail yard
contaminated snow storage on slope above ditch

Remedial action required (including any interim steps)

clean all contaminated snow and waste from slope which runs into #9 ditch

Abatement time (including interim steps)

One week or no later than 12:00 PM on 1/16/86