7-13-89
7/25

0013

RUS

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/006
Inspection Date 6/30/89

Permittee/Operator Name Cyprus-Plateau Mining Co.
Business Address P.O Drawer PMC
City Price State Utah Zip 84501
Mine Starpoint ☐ Surface ☒ Underground ☐ Other
County Carbon State Ut
Company Official(s) Ben Grimes
State Official(s) Bill Malencik
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 5/18/89 Weather conditions Warm/Clear
Acreage 7200 ☐ Permitted 221.65 ☐ Disturbed ☐ Regraded ☐ Seeded 221.65 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☒
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 6/30/89

Please number comments to correspond with topics on previous page.

General Comments This partial inspection focused on (1) followup items identified in the inspection of 5/18/89, and (2) field examination of drill sites and areas of recent subsidence.

Diversions Culvert 42D had been cleaned as suggested by the previous inspection.

Coal Processing Waste. All abatement work on the refuse pile ditches has been completed and terminated on 5/30/89. The work consisted of sloping & grading ditches #16 & 76; installing silt fences in ditch #8. The foregoing all related to and responded to NOV 89-26-17-1.

Contemporaneous Reclamation. Several drill pads were regraded and seeded last fall, others regraded this year and shall be seeded this fall. Last fall seeding shows some promise for vegetal reestablishment, but at least another growing season is required before better establishment judgements can be made.

Subsidence. Mr. Grimes directed me to several areas of recent subsidence. In most areas general subsidence took place without obvious surface evidence, some up to six feet of displacement. While in other areas large cracks had occurred which the company filled and fenced. Also such areas were signed

Copy of report mailed to Cyprus-Plateau / Ben Grimes
SLC FOR: OSM / Brian Smith; DOGM Joe Helfrich

Copy of report ~~given~~ filed to PFO

Inspector's signature Wm. J. Malinick No. 26.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

7/10/89

DOGM/IR-2 an equal opportunity employer 11/86 001049