0021

5-23
7125

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RUS

inspection report

Permit No. ACT/007/006

Inspection Date April 14 & 17, 1989

Permittee/Operator Name Cyprus-Plateau Mining Co.

Business Address P.O. Drawer PMC.

City Price State Ut Zip 84501

Mine Star Point ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut

Company Official(s) Bob Lauman (4/14) Ben Grimes (4/17)

State Official(s) Bill Malencik

Time of inspection 4/14 7:15 ☒ a.m. ☐ p.m. to 2pm 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete 4 pm 1

Date of last inspection March 1, 1989 Weather conditions Clear/Warm.

Acreage 7200 ☐ Permitted 221 ☐ Disturbed ☐ Regraded ☐ Seeded 221 ☐ Bonded

Enforcement Action Potential NOV on Refuse Pile Ditches/Pending TDN.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date April 14 & 17, 1989.

Please number comments to correspond with topics on previous page.

General Comments. Bob Lauman advised me that Ben Grimes was underground on the longwall/stream study. He suggested that I accompany Ben to the study area monday morning, April 17. Further he stated they would invite SLC/DOGM personnel on the underground trip. Monday morning was advised by Rick Smith that it would not be necessary to go underground, however, Tom Munson & Darin Whalen would accompany mine personnel underground.

Diversion: Ben Grimes and the undersigned walked the refuse pile ditches. Advised Mr Grimes that DOGM's reponse to the Sept 1988 TDN had been declared unacceptable by OSM. A followup TDN was issued by OSM April 7, 1989. Also, that DOGM may issue a notice of violation for the reasons that some refuse ditches were not designed now documented in the MRP in accordance with the Utah Coal Mine Regulations. Also because of the expansion of the coal refuse pile and the construction of sediment pond #9

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 4/14&17/89

Please number comments to correspond with topics on previous page.

the operator may want to reevaluate water conveyance systems about the refuse pile

Sediment Ponds: Sediment ponds and small area exemptions were checked.

Other Sediment Control: Check dams were observed for functionability. Several check dams had recently been cleaned & no problems were noted.

SLC For: OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report mailed to Cyprus Plateau Mining Co./Ben Grimes

Copy of report ~~given to~~ filed: PFO

Inspector's signature Wm. J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

4/26/89.