8-23-89
7125

0022

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gd RVS

inspection report

Permit No. ACT/007/006

Inspection Date April 14 & 17, 1989

Permittee/Operator Name Cyprus-Plateau Mining Co.

Business Address P.O. Drawer PMC

City Price State Ut Zip 84501

Mine Star Point ☐ Surface ☒ Underground ☐ Other

County Carbon State

Company Official(s) Bob Lauman & Ben Grimes

State Official(s) Bill Malencik

Time of inspection 4/14-1989 - 2pm - 4pm; 4/17 - 7:30 a.m - 2pm. ☐ a.m. ☐ p.m. to ___:___ ☐ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection March 1, 1989 Weather conditions Clear & Warm

Acreage 7200 ☐ Permitted 221 ☐ Disturbed ☐ Regraded ☐ Seeded 221 ☐ Bonded

Enforcement Action POTENTIAL NOV ON DIVERSIONS

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date April 14 & 17, 1989.

Please number comments to correspond with topics on previous page.

General Comments. This partial inspection covered part of two days.

The operator on April 14 advised me that Ben Grimes was underground. Further that he would appreciate if I could return monday to complete the inspection and check a compliance situation underground. Upon my arrival at the mine a phone call was pending from Rick Smith. He advised me that Tom Munson would review the in-mine situation on tuesday and it would not be necessary to include the item in my inspection

Diversion The diversions associated with the coal refuse pile and subset of TDN that is currently pending was field checked. I notified Ben Grimes that a potential NOV exists based on information collectively in our possessions. However, I advised him I would not issue the NOV until I checked with our SLC office

Sediment Ponds. Sediment ponds were checked together with areas not draining into sediment ponds

Other Sediment Control. Several check dams were checked and showed evidence of having been cleaned recently.

Copy of report mailed to { CYPRUS-PLATEAU / Ben Grimes
OSM / Brain Smith; DOGM / Joe Helfrich

Copy of report ~~given~~ filed to PFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

4/18/89

DOGM/IR-2

an equal opportunity employer

11/86 001049