



Cyprus Plateau Mining Corporation
P.O. Drawer PMC
Price, Utah 84501
(801) 637-2875

March 29, 1990

RECEIVED
APR 02 1990

Mr. Lowell Braxton
Utah Department of Natural Resources
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

DIVISION OF
OIL, GAS & MINING

Dear Mr. Braxton:

Re: **Annual Reports**

You will find enclosed copies of Cyprus Plateau Mining Corporation annual reports, mine maps, and the annual report form.

These enclosures consist of the following:

- DOGM Annual Report Form
- Subsidence Monitoring Report 1989
- 1989 Annual Reclamation Monitoring Report
- Annual Hydrologic Report 1989
- Wattis Seam Mine Map - Date 2/26/90
- Third Seam Mine Map - Date 2/26/90


Precipitation data can be found on Table 45 in the Annual Hydrologic Report.

All stipulations have been resolved and incorporated into the CPMC MRP.

Mr. Lowell Braxton
Page Two
March 29, 1990

A copy of the Annual Hydrologic Report and the Subsidence Monitoring Report have been sent to the Manti LaSal National Forest office in Price.

Respectfully,


Ben Grimes
Sr. Environmental Engineer

/sd

Enclosures

File: ENV 2-6
Chrono: BG900306

COAL MINING AND RECLAMATION OPERATIONS FOR 1989
(Authority UMC 784)

(Must be submitted to the Division by March 31, 1990)

State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, Utah 84180-1203

(801) 538-5340

Operator: Cyprus Plateau Mining Corporation
Mine Name: Star Point Mines
Mailing Address: P.O. Drawer PMC
Company Representative: Ben Grimes
Permit Number: ACT/007/006
Date of Most Recent Permanent Program Permit: August 7, 1987
Quantity of Coal Mined (tonnage) 1989: 1.8 Million

Attach Updated Mine Sequence Map.

All monitoring activities during the report period must be submitted with this report (including, but not limited to):

- A. Summarized Water Monitoring Data
- B. Precipitation or Other Climatological Data
- C. Subsidence Monitoring Report
- D. Vegetation Data (test plots) or Revegetation Success Monitoring (includes interim and final)
- E. Permit Stipulation Status