UTAH
NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gcl



# inspection report

Permit No. ACT/007/006
Inspection Date 12/11/90

Permittee/Operator Name Cyprus Plateau Mining Company
Business Address P.O. Drawer PMC
City Price State UTAH Zip 84501
Mine STARPOINT MINES ☐ Surface ☑ Underground ☐ Other
County Carbon State
Company Official(s) MENCO COPINGA
State Official(s) PAMELA GRUBAUGH-LITTIG
Time of inspection 8:15 ☑ a.m. ☐ p.m. to 10:00 ☑ a.m. ☐ p.m. ☑ Partial ☐ Complete
Date of last inspection 11/10/90 Weather conditions Clear and Cool
Acreage 7200 ☑ Permitted 221 ☑ Disturbed ☐ Regraded ☐ Seeded 221 ☑ Bonded
Enforcement Action NONE

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☐ | ☐ | ☐ | ☐ |
| 2. Signs and markers | ☑ | ☐ | ☐ | ☐ |
| 3. Topsoil | ☑ | ☐ | ☐ | ☐ |
| 4. Hydrologic balance | | | | |
| — Stream channel diversions | ☐ | ☐ | ☐ | ☐ |
| — Diversions | ☐ | ☐ | ☐ | ☐ |
| — Sediment ponds and impoundments | ☐ | ☐ | ☐ | ☐ |
| — Other sediment control measures | ☐ | ☐ | ☐ | ☐ |
| — Surface and groundwater monitoring | ☐ | ☐ | ☐ | ☐ |
| — Effluent limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☑ | ☐ | ☐ | ☑ |
| 6. Development waste and spoil disposal | ☐ | ☐ | ☐ | ☐ |
| 7. Coal processing waste | ☑ | ☐ | ☐ | ☑ |
| 8. Noncoal waste | ☐ | ☐ | ☐ | ☐ |
| 9. Protection of fish, wildlife, and related environmental values | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☐ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☑ | ☐ | ☐ | ☑ |
| 12. Backfilling and grading | ☐ | ☐ | ☐ | ☐ |
| 13. Revegetation | ☑ | ☐ | ☐ | ☑ |
| 14. Subsidence control | ☐ | ☐ | ☐ | ☐ |
| 15. Cessation of operations | ☐ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| a Construction | ☐ | ☐ | ☐ | ☐ |
| b Drainage controls | ☑ | ☐ | ☐ | ☑ |
| c Surfacing | ☐ | ☐ | ☐ | ☐ |
| d Maintenance | ☐ | ☐ | ☐ | ☐ |
| 17. Other transportation facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☐ | ☐ | ☐ | ☐ |

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 12-11-90

Please number comments to correspond with topics on previous page.

5. Explosives magazine was properly marked and in area as noted on surface facilities map.

13. & 11. Contemporaneous reclamation of #1 Mine chas vegetation established. Noted some timbers that should be removed and conveyor ~~area buildin~~ foundation area that should be broken up and ~~ma~~ buried. Advised Mr. Copinga that this should be done.

16. b. Road drainage controls are in good working order.

7. Drove out on coal processing waste lifts. The wash plant is down for repairs so ~~all~~ there ~~was no~~ were no stacks of materials being dried. All lifts had been compacted.

Copy of report mailed to Ben Grimes, Cyprus Plateau, John Kathmann, OSM AFO

Copy of report given to Joe Helfrich

Inspector's signature Pamela Grubaugh-Littig 12/11/90 No. 20

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049