0019

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

get page

inspection report

Permit No. ACT/007/006

Inspection Date 3/15/90

Permittee/Operator Name CYPRUS PLATEAU MINING COMPANY

Business Address P.O [redacted] DRAWER PMC

City PRICE State UTAH Zip 84501

Mine [redacted] STARPOINT ☐ Surface ☒ Underground ☐ Other

County CARBON State UTAH

Company Official(s) BEN GRIMES

State Official(s) TOM MUNSON, JESS KELLEY

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 11:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 2/8/90 Weather conditions SUNNY

Acreage 7200 ☒ Permitted 221 ☒ Disturbed ☐ Regraded ☐ Seeded 221 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☒
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☐
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 3/15/90

Please number comments to correspond with topics on previous page.

4a) Diversion 76 was inspected and it was still snowed in at most points along the diversion. Diversion 9A as referenced in the last inspection report was also snowed in and will be inspected at the next inspection in April.

13) The test plots established last year were covered with snow and in some places 4 feet of snow was apparent.

As the snow melts, ~~and~~ ditches and culverts will have to be inspected for spring cleaning and repair where necessary.

17) a revised bond was submitted for review by the division on 3/19/90

Copy of report mailed to CYPRUS PLATEAU/BEN GRIMES SLC-OSM/BRIAN SMITH; DOGM/JOE HELFRICH

Copy of report given to PFO

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE