

Document Information Form

Mine Number: C007/006

File Name: Incoming

To: DOGM

From:

Person N/A

Company OFFICE OF SURFACE MINING RECLAMATION AND ENFORCEMENT

Date Sent: MARCH 18, 1991

Explanation:

TEN-DAY NOTICE.

cc:

File in: C/ 007, 006, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

orig: mine file cc LAB, PGL, Jch VB

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE

Originating Office:
Surface Mining
Albuquerque Field Office
625 Silver Ave, SW
Suite 310
Albuquerque New Mexico
Telephone Number: 505-766-1486

Number: X-91-02-244-5 TV 2

Ten-Day Notice to the State of Utah

You are notified that, as a result of oversight inspection (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Cyprus-Plataan Mining Co County: Carbon Surface
(Or Operator if No Permit)
Mailing Address: PO Box PMC ; Price, Utah Underground
Permit Number: ACT/007/06 Mine Name: Star Point Other

NATURE OF VIOLATION AND LOCATION: Failure of the permittee to comply with the terms and conditions of the permit. (stockpiling of coal in a non-permitted area)

Castle Gate coal pile on processing waste pile Section of State Law, Regulation or Permit R614-300-143
Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: ~~Failure to~~ Diversion of surface drainage over the outslope of the refuse pile

outslope on the southern end of the coarse Section of State Law, Regulation or Permit R614-301-746-212
Condition believed to have been violated:

refuse pile below two working faces.
NATURE OF VIOLATION AND LOCATION:

Section of State Law, Regulation or Permit
Condition believed to have been violated: MAR 18 1991

RECEIVED

Remarks or Recommendations:

DIVISION OF OIL GAS & MINING

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No 0061 Date _____
In Cl 007, 006, Incoming _____
For additional information

Date of Notice: 03/15/91
certified mail #
P 965 799 043

JTS
#244

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE

Originating Office:
Surface Mining
Albuquerque Field Office
625 Silver Ave, SW
Suite 310
Albuquerque New Mexico
Telephone Number: 505-766-1486

Number: X-91-02-244-5 TV 2

Ten-Day Notice to the State of Utah

You are notified that, as a result of oversight inspection (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Cyprus-Plataan Mining Co County: Carbon
(Or Operator if No Permit)
Mailing Address: PO Box PMC ; Price, Utah
Permit Number: ACT/007/06 Mine Name: Star Point

- Surface
- Underground
- Other

NATURE OF VIOLATION AND LOCATION: Failure of the permittee to comply with the terms and conditions of the permit. (stock piling of coal in a non-permitted area)

Castle Gate coal pile on processing waste pile Section of State Law, Regulation or Permit R614-300-143
Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: ~~Failure to~~ Diversion of surface drainage over the outslope of the refuse pile

outslope on the southern end of the coarse Section of State Law, Regulation or Permit R614-301-746-212
Condition believed to have been violated:

refuse pile below two working faces.
NATURE OF VIOLATION AND LOCATION:

Section of State Law, Regulation or Permit
Condition believed to have been violated:

RECEIVED

MAR 18 1991

Remarks or Recommendations:

DIVISION OF
OIL GAS & MINING

Date of Notice: 03/15/91
certified mail #
P 965 799 043

Signature of Authorized Rep.: Gary Fritz
Print Name and ID: Gary Fritz #244