



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

qh 00271

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

PERMIT NO.: ACT/007/006-91B Inspection Date: October 31, 1991  
 Permittee and/or Operators Name: Cypress-Plateau Mining Corp.  
 Business Address: P.O. Drawer PMC  
 City: Price State: Utah Zip: 84501  
 Mine Name: Mohrland Exploration Sites  
 County: Carbon State: Utah  
 Type of Mining Activity: Underground Surface Other XX  
 Company Official (s): Ben Grimes  
 State Officials (s): Stephen J. Demczak  
 Time of Inspection: 9:00 (X) a.m. ( ) p.m. to 1:00 ( ) a.m. (X) p.m.  
 Partial Complete: XX Date of Last Inspection: \_\_\_\_\_  
 Weather Conditions: Cool 20's 4" snow  
 Acreage: Permitted \_\_\_\_\_ Disturbed \_\_\_\_\_ Regraded \_\_\_\_\_ Seeded \_\_\_\_\_  
 Bonded \_\_\_\_\_ Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( X )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( X )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT COMMENTS  
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/006-91B INSPECTION DATE October 31, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits -

- a. The permit was granted on May 30, 1991 by DOGM. The permit is for exploration of less than 250 tons. The Mohrland Exploration Sites were drill holes (core drilling sites) for determining the feasibility of potentially opening a coal mine at Mohrland.
- b. The drill hole sites were completely reclaimed in late August. The inspection showed the ground has been ripped and seeded, and a fence was installed surrounding the perimeter of the disturbed area. The fence is to prohibit wildlife from grazing on the future vegetation.
- c. The drill holes presently are left in three categories:
  1. Filled and sealed.
  2. Capped and locked for potential use as a water monitoring station.
  3. Capped and locked for potential subsidence evaluation stations.

A future date should be determined for the existing drill holes which are potentially to be used for water monitoring and subsidence - to be sealed if no coal mine is developed.

Copy of report:

Mailed to: Cypress Plateau Mining Corp.  
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)  
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak  
Date: 11-1-91

