

0009



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

pk 0271

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

PERMIT NO.: ACT/007/006-91B Inspection Date: October 31, 1991
 Permittee and/or Operators Name: Cypress-Plateau Mining Corp.
 Business Address: P.O. Drawer PMC
 City: Price State: Utah Zip: 84501
 Mine Name: Mohrland Exploration Sites
 County: Carbon State: Utah
 Type of Mining Activity: Underground Surface Other XX
 Company Official (s): Ben Grimes
 State Officials (s): Stephen J. Demczak
 Time of Inspection: 9:00 (X) a.m. () p.m. to 1:00 () a.m. (X) p.m.
 Partial Complete: XX Date of Last Inspection: _____
 Weather Conditions: Cool 20's 4" snow
 Acreage: Permitted _____ Disturbed _____ Regraded _____ Seeded _____
 Bonded _____ Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/006-91B INSPECTION DATE October 31, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits -

- a. The permit was granted on May 30, 1991 by DOGM. The permit is for exploration of less than 250 tons. The Mohrland Exploration Sites were drill holes (core drilling sites) for determining the feasibility of potentially opening a coal mine at Mohrland.
- b. The drill hole sites were completely reclaimed in late August. The inspection showed the ground has been ripped and seeded, and a fence was installed surrounding the perimeter of the disturbed area. The fence is to prohibit wildlife from grazing on the future vegetation.
- c. The drill holes presently are left in three categories:
 1. Filled and sealed.
 2. Capped and locked for potential use as a water monitoring station.
 3. Capped and locked for potential subsidence evaluation stations.

A future date should be determined for the existing drill holes which are potentially to be used for water monitoring and subsidence - to be sealed if no coal mine is developed.

Copy of report:

Mailed to: Cypress Plateau Mining Corp.
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak
Date: 11-1-91

