0013

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gpl pgl

inspection report

Permit No. ACT/007/006

Inspection Date 10/4/91

Permittee/Operator Name Cyprus Plateau Mining Corp.

Business Address P.O. Drawer PMC

City Price State Ut Zip 84501

Mine Star Point/Exploratory Pits ☐ Surface ☐ Underground ☐ Other

County Carbon & Emery State Ut

Company Official(s) Ben Grunles

State Official(s) Bill Malencik

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection N/A Weather conditions Clear/Cool

Acreage 7200 ☒ Permitted 221 ☒ Disturbed ☐ Regraded ☐ Seeded 221 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☒
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 10/4/91

Please number comments to correspond with topics on previous page.

This inspection covered exploration pits on gentry Mtn lying in section 14, Twp 15S, R. 7E, SLPM. Twenty-two sites were proposed. The project was approved as a condition of the subsidence and for other information relating to faults and mining methods. The pit disturbed area was paced and the maximum size was 20' x 40'. The field investigation and facts derived therefrom are as follows:

(1) The sites are hard to detect in the field. The pits have been filled and seeded. Only where the pits were in a sagebrush type and with the benefit of a map these sites are more discernible.

(2) All the exploratory sites have been reclaimed and
  (a) no erosion was observed
  (b) the disturbed pits have been graded and fits in with the general lay of the land and,
  (c) the disturbed areas have a good vegetation cover.

(3) Pits twenty two in number as approved covered transects 89-R-6 to 89-R-14

A review of the record shows that all exploratory sites have been covered by a field inspection and appropriate reports.

Copy of report mailed to CPMC/Ben Grimes; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed in PFO/w attachments (field notes)

Inspector's signature [signature] No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

10/30/91

DOGM/IR-2

an equal opportunity employer

11/86 001049