0022

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/006

Inspection Date 7/30/91

Permittee/Operator Name Cyprus-Plateau Mining Corp.

Business Address P.O. Drawer PMC

City Price State UT Zip 84501

Mine Star Point ☐ Surface ☒ Underground ☐ Other

County Carbon State UT

Company Official(s) Ben Grimes

State Official(s) Susan White

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 6/27/91 Weather conditions Fair to partly cloudy, warm

Acreage 7200 ☐ Permitted 221 ☐ Disturbed ☐ Regraded ☐ Seeded 221 ☐ Bonded

Enforcement Action AVS Check - NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☑
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a – Stream channel diversions	☐	☐	☐	☐
b – Diversions	☐	☐	☐	☐
c – Sediment ponds and impoundments	☐	☐	☐	☐
d – Other sediment control measures	☐	☐	☐	☐
e – Surface and groundwater monitoring	☑	☐	☐	☑
f – Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☑	☐	☐	☑
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☑	☐	☐	☑
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 7/30/91

Please number comments to correspond with topics on previous page.

2. Signs and Markers
AVS Inspection: The permit listed:
PMC
Plateau Mining Company
P.O. Drawer PMC
Price, UT (801)637-2875
as the operator. The entrance sign listed: CPMC
Cyprus-Plateau Mining Corp.
Same address
637-2375

4.e. Surface and Groundwater Monitoring
I accompanied Mr. Grimes to water well 86-26-6. Water level was determined by displacing the water with nitrogen and then reading the pressure.

11. The 1989 test plots adjacent to the conveyor were observed. Vegetation cover and diversity appeared

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 7/30/91

Please number comments to correspond with topics on previous page.

to be more dependant on soil types than on the mulch treatment.

14. Subsidence Control

The subsidence cracks on Hoag Ridge were observed. Mr. Grimes said The company discovered the cracks in June while in a helicopter. The area had pillars removed some 4-6 months prior to discovery. Two cracks run about 400' across a ridge. The area is ~~in~~ on a very steep mountain side. The company fenced the cracks to prevent injury to hunters which may use the area ~~this~~ The cracks are on Forest Service property.

Copy of report mailed to Ben Grimes, John Kathman

Copy of report given to Joe Helfrich

Inspector's signature Susan M. White No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE