0027

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 8:00 to 10:00 AM
30 April 1991

Permittee and/or Operator's Name: Cyprus-Plateau
Business Address: Post Office Drawer PMC, Price, Utah 84501
Mine Name: Star Point Permit Number: ACT/007/006
Type of Mining Activity: Underground X Surface__ Other__
County: Emery Company Official(s): Ben Grimes, Robert Rowley
State Officials(s): Pam Grubaugh-Littig, Tom Munson, Hugh Klein
Federal Official(s): N/A
Partial: X Complete: ___ Date of last Inspection: 7 February 1991
Weather Conditions: clear and cool
Acreage: Permitted 7200 Disturbed 221 Regraded_ Seeded_ Bonded 221
Enforcement Action: N/A

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(x)	( )	( )	( )
2. SIGNS AND MARKERS	(x)	( )	( )	( )
3. TOPSOIL	(x)	( )	( )	(x)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(x)	( )	( )	( )
b. DIVERSIONS	(x)	( )	( )	(x)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(x)	( )	( )	(x)
d. OTHER SEDIMENT CONTROL MEASURES	(x)	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	(x)	( )	( )	( )
f. EFFLUENT LIMITATIONS	(x)	( )	( )	(x)
5. EXPLOSIVES	(x)	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	(x)	( )	( )	( )
7. COAL PROCESSING WASTE	(x)	( )	( )	( )
8. NONCOAL WASTE	(x)	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(x)	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	(x)	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	(x)	( )	( )	( )
12. BACKFILLING AND GRADING	(x)	( )	( )	( )
13. REVEGETATION	(x)	( )	( )	( )
14. SUBSIDENCE CONTROL	(x)	( )	( )	( )
15. CESSATION OF OPERATIONS	(x)	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	(x)	( )	( )	( )
b. DRAINAGE CONTROLS	(x)	( )	( )	( )
c. SURFACING	(x)	( )	( )	( )
d. MAINTENANCE	(x)	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	(x)	( )	( )	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	(x)	( )	( )	( )

an equal opportunity employer

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/007/ 006 DATE OF INSPECTION: 30 April 1991

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

The weather was clear and cool. All permits were visible at the permit area boundaries.

The 1990 annual report was received prior to departure from the site.

3) Topsoil

The abatement work required by NOV 91-25-1-3 has been performed. Additional work is required in order to reseed areas disturbed during the abatement work. This was discussed and will take place in a timely manner.

4b) Diversions

Trash racks and culverts were observed to be clean and free of debris.

Ditch 16 A-E has been grouted and appears to be adequate in terms of controlling erosive velocities. Drainage improvements outlined in the February 22, 1991 letter from Cyprus Plateau Mining Company to the Division have been completed.

4c) Sediment ponds and impoundments

NOV 91-25-3-3 was issued due to improper sediment pond construction as it relates to trash racks and oil skimmers. The trash racks and oil skimmers on Pond 3 have been modified so as to comply with the terms for abating the NOV. The work on the remaining ponds has not yet been completed. In order for the abatement requirements to be satisfied, the remaining work must be completed by 5:00 PM, 30 May 1991.

4f) Effluent limitations

Ben Grimes communicated to the undersigned inspector that Pond 9 discharged on April 6, 1991. Analytical results of this are expected to appear in the second quarter (1991) water monitoring report.

Copy of this Report:
Mailed to: Ben Grimes CPMC
Brian Smith OSM
Given to: Pam Grubaugh-Littig DOGM
Tom Munson DOGM
Joe Helfrich DOGM

Inspector's Signature & Number: #40
Date: 10 May 1991