



pgk

NO. N

~~26730~~

01-25-01-03

notice of violation

To the following Permittee or Operator:

Name CYPRUS - PLATEAU MINING COMPANY

Mine STAR POINT MINE Surface Underground Other

County CARBON State UTAH Telephone _____

Mailing Address: P.O. DRAWER PMC

State Permit No. ACT/007/006

Ownership Category State 7200 Federal Fee Mixed

Date of inspection 3/7-8, 19____

Time of inspection 9:30 2/7 a.m. p.m. to 1:00 3/8 a.m. p.m.

Operator Name (other than Permittee) MENCO COPINGA

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing 3/8/91 Time of service/ mailing 1:00 a.m. p.m.

MENCO COPINGA
Permittee/Operator representative
Menas Copinga
Signature

Project Engineer
Title

TOM MUNSON
Division of Oil, Gas & Mining representative
Tom Munson
Signature

RECLAMATION SPECIALIST
Title
25
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 91-25-1-3

Violation No. 1 of 3

Nature of violation

FAILURE TO PROTECT TOPSOIL STORAGE PILE
FROM WATER AND WIND EROSION.

Provisions of act, regulations or permit violated

40-10-17(2)(e), R614-301-234.230

Portion of operation to which notice applies

TOP SOIL PILE

Remedial action required (including any interim steps)

REPAIR AND FILL IN ANY HOLES IN CONTOUR
FURROWS AND PLACE SILT FENCE AT TOE
OF PILE FOR ADDITIONAL PROTECTION.

Abatement time (including interim steps)

MARCH 21, 1991 TO COMPLETE ALL TASKS BY
5:00 PM



NOTICE OF VIOLATION NO. N 91-25-1-3

Violation No. 2 of 3

Nature of violation

FAILURE TO MAINTAIN DIVERSIONS AND ASSOCIATED
CULVERTS. INLETS BLOKED WITH DEBRIS.

Provisions of act, regulations or permit violated

R614-301-742.312

Portion of operation to which notice applies

INLETS TO CULVERTS ON DITCH 10, SEDIMENT
TRAP CULVERT ON DITCH 16E

Remedial action required (including any interim steps)

CLEAN ALL TRASH RACKS AND INLETS OF CULVERTS
OF DEBRIS AND RESTORE FLOW TO CULVERT ON
DITCH 10 D

Abatement time (including interim steps)

COMPLETE WORK BY MARCH 12, 1991 BY 5:00 PM



NOTICE OF VIOLATION NO. N 91-25-3 - 3

Violation No. 3 of 3

Nature of violation

FAILURE TO CONSTRUCT SEDIMENT POND #1, 3, 4, 5,
6, 7, 8 AS APPROVED. TRASH RACKS AND ANTI-
VORTEX DEVICES NOT INSTALLED AS SHOWN
ON DRAWINGS

Provisions of act, regulations or permit violated

R614-301-512.240

Portion of operation to which notice applies

SEDIMENT POND # 1, 3, 4, 5, 6, 7, 8

Remedial action required (including any interim steps)

CONSTRUCTION POND AS SHOWN ON CERTIFIED DRAWINGS

Abatement time (including interim steps)

HAVE ALL SEDIMENT POND CONSTRUCTED AS SHOWN
ON CERTIFIED DRAWINGS BY APRIL 5, 1991 BY 5:00 PM
AND PROVIDE AS-BUILT DRAWINGS TO THE DIVISION
BY THIS DATE AND TIME