0001

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. Act/007/006
Inspection Date 12/9/92

Permittee/Operator Name Cyprus Plateau Mining Corp.
Business Address P.O. Drawer PMC
City Price State Ut Zip 84501
Mine Star Point ☐ Surface ☒ Underground ☐ Other
County Carbon State Ut
Company Official(s) Ben Grimes
State Official(s) Bill Malencik
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 11/11-12/92 Weather conditions Cloudy / Mine Site Snow Covered
Acreage 7200 ☐ Permitted 221 ☐ Disturbed ☐ Regraded ☐ Seeded 221 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/007/006

Inspection Date 12/9/92

Please number comments to correspond with topics on previous page.

General Comments. The mine site was snowed covered. Snow the night before covered the mine site and most of the environmental control measures. As a result thereof the field inspection was limited to a check of the roads and snow removal operations

Signs & Markers. ID signs were in place at each primary point of access from public roads.

Sediment Ponds & Impoundments. Observed ponds #2, 8, & 9.

Roads. Roads on the mine site had been plowed; the county road had not been plowed at the start of the inspection. The road had been plowed when I departed.

Records:

- Water monitoring was discussed with the operator in line with suggestions made on the 11/11-12/92 inspection. The operator stated he plans to clarify and amend the mine water monitoring program.
- Mr. Grimes explained and demonstrated the new mine environmental records system.

Copy of report mailed to CPMC/Ben Grimes; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

12/14/92