



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: 24 June 1992  
08:30 to 13:00

Permittee and/or Operator's Name: Cyprus Plateau Mining Company  
Business Address: P.O. Drawer PMC Price, Utah 84501  
Mine Name: Star Point Permit Number: ACT/007/006  
Type of Mining Activity: Underground X Surface      Other       
County: Carbon Company Official(s): Ben Grimes  
State Officials(s): Jess Kelley  
Federal Official(s): None  
Partial: X Complete:      Date of last Inspection: 12 May 1992  
Weather Conditions: Sunny and hot  
Acreage: Permitted-7200 Disturbed-221 Regraded-0 Seeded-0  
Bonded-221 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	(X)	( )	( )	(X)
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	(X)	( )	( )	(X)
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	(X)	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	(X)	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/006 DATE OF INSPECTION: 24 June 1992

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS

Site identification signs are in place and good repair. Disturbed area boundary markers are in place and in good condition.

4. HYDROLOGIC BALANCE

(b) Diversions--Disturbed and undisturbed ditches and culverts are clean and in good repair.

(c) Sediment Ponds and Impoundments--Ponds 1,2,3,5,6,8 and 9 all contain some water, but none has discharged. Ponds 4 and 7 are dry. Pond 4 was cleaned during the summer of 1991. Pond 7 is filled to the 45% level with sediment and will be cleaned out during the summer of 1992. All ponds are clean and in good repair and free from erosion damage.

The sediment trap at the first bend of the main road below the main facilities pad is undergoing cleaning.

11. CONTEMPORANEOUS RECLAMATION

The entire Gentry Mountain road, the old portal area, and the storage yard above Pond 3 were inspected. This area will be reclaimed during final reclamation and the present main road will become the new Gentry Mountain access road and be returned to the jurisdiction of Carbon County. To date, some minor regrading has taken place in the storage yard area and the area has been seeded for interim erosion control, but the area has not been finally reclaimed, nor has bond release been sought for the area.

Copy of this Report:

Mailed to: Ben Grimes/Cyprus Plateau; Bernie Freeman/OSM  
Given to: Joe Helfrich (DOGM); Price Field Office/DOGM

Inspector's Signature: Gene W. Kelley #34 Date: 6/26/92