0004

STATE OF UTAH
NATURAL RESOURCES
Division of Oil, Gas & Mining

3 Triad Center · Suite 350 · Salt Lake City, UT 84180-1203 · (801) 538-5340

gh pgl

inspection report

☑ Partial
☐ Complete
☐ Exploration

Inspection Date: Nov. 8 & 9, 1993

Time: 9:00 ☒am ☐pm to 2:00 ☐am ☒pm

Date of Last Inspection: 10/26/93

Mine Name: Starpoint County: Carbon Permit Number: Act 007/006

Permittee and/or Operator's Name: Cyprus Mining Corporation

Business Address: P.O. Drawer, PMC, Price, Utah 84501

Type of Mining Activity: ☑ Underground ☐ Surface ☐ Prep. Plant ☐ Other

State Officials(s): Bill Malencik

Company Official(s): John Boxle, Ben Grimes

Federal Official(s): N/A

Weather Conditions: Clear / Cold - Skiff snow on north side of mine site

Existing Acreage: Permitted-7200 Disturbed-220 Regraded-____ Seeded-____ Bonded-220

Increased/Decreased: Permitted-____ Disturbed-____ Regraded-____ Seeded-____ Bonded-____

Status: ☐ Exploration / ☑ Active / ☐ Inactive / ☐ Temporary Cessation / ☐ Bond Forfeiture

☐ Reclamation (☐ Phase I / ☐ Phase II / ☐ Final Bond Release / ☐ Liability____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	☐	☐	☐	☐
2. SIGNS AND MARKERS	☑	☐	☑	☐
3. TOPSOIL	☑	☐	☐	☐
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	☑	☐	☑	☐
b. SEDIMENT PONDS AND IMPOUNDMENTS	☑	☐	☑	☐
c. OTHER SEDIMENT CONTROL MEASURES	☑	☐	☐	☐
d. WATER MONITORING	☐	☐	☐	☐
e. EFFLUENT LIMITATIONS	☐	☐	☐	☐
5. EXPLOSIVES	☑	☐	☐	☐
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	☐	☐	☐	☐
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	☑	☐	☐	☐
8. NONCOAL WASTE	☑	☐	☐	☐
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	☐	☐	☐	☐
10. SLIDES AND OTHER DAMAGE	☐	☐	☐	☐
11. CONTEMPORANEOUS RECLAMATION	☐	☐	☐	☐
12. BACKFILLING AND GRADING	☐	☐	☐	☐
13. REVEGETATION	☐	☐	☐	☐
14. SUBSIDENCE CONTROL	☐	☐	☐	☐
15. CESSATION OF OPERATIONS	☐	☐	☐	☐
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	☑	☐	☑	☐
b. DRAINAGE CONTROLS	☑	☐	☑	☐
17. OTHER TRANSPORTATION FACILITIES	☐	☐	☐	☐
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	☐	☐	☐	☐
19. AVS CHECK (4th Quarter-April, May, June)____(date)	☐	☐	☐	☐
20. AIR QUALITY PERMIT	☐	☐	☐	☐
21. BONDING & INSURANCE	☐	☐	☐	☐

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/007/006

Inspection Date 11/26/93

Please number comments to correspond with topics on previous page.

General Comments: Partial inspection covered parts of two days. The field segment was performed on October 9. The permittee was represented by Ben Grimes.

Signs & Markers: Observed I.D. sign at the mine haul road where it interfaces with the county road. Disturbed markers were observed at the coal silo area and the upper mine pad.

Diversions: The operator performed additional work before the inspection on diversions 82A and 82B. Because of the lay of the land the diversions were constructed to a depth exceeding the design depth by about 2'. The design depth was +1'.

Sediment Ponds: Observed ponds 2, 3, 4, 7, & 9. All ponds noted above contained runoff except for pond 7. Pond 8 also contained runoff.

Road: The haul road amendment to widening the road near the truck loadout has not been completed. The only remaining work consists of blacktopping the road. The road has been graveled. The operator stated they would consider amending the road design deleting the blacktop. Suggested the operator take some definitive action to finalize this project.

Copy of report mailed to Starpoint/Ben Grimes; OSM/Marcia Petta; DOGM/Joe Helfrich

Copy of report given to: filed PEO

Inspector's signature M. J. Kalmick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

11/10/93

DOGM/IR-2

an equal opportunity employer

11/86 001049