



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Page 1

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 7/28/93 /11:30-1:30
Date of Last Inspection: 6/30/93

Mine Name: Star Point County: Carbon Permit Number: ACT/007/006
Permittee and/or Operator's Name: Cyprus Plateau Mining Corporation
Business Address: P.O. Drawer PMC, Price, Utah 84501
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Susan White
Company Official(s): Ben Grimes and Mike Kelley
Federal Official(s): None
Weather Conditions: Sunny and warm
Existing Acreage: Permitted-7200 Disturbed-220 Regraded- Seeded- Bonded-221
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation ( Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK (4th Quarter-April, May, June) (date); 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.

## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 7/28/93

(Comments are Numbered to Correspond with Topics Listed Above)

3. Topsoil - The operator was asked to reseed the topsoil pile in areas of weeds. The subsoil pile did not have a complete perimeter berm, although no soil loss was evident.

4a. Diversions- Violation N93-25-4-1 was issued at this inspection by Tom Munson. Ditch 74B was reconstructed without approval and not according to the approved plan.

4b. Sediment Ponds and Impoundments- Ponds 2, 7, and 9 had been cleaned.

13. Revegetation - The road to the mine office is to be left as a county road for the postmining land use. The operator has successfully revegetated most of the cut and fill slopes along the road, however numerous small areas along the road have poor vegetation establishment. These areas are mostly steep loose soils and/or shaley compacted soils. Most of the revegetation efforts occurred approximately 10 years ago. The need for continued efforts at vegetation establishment was emphasized to the operator.

20. Air Quality - The operator was reminded of the air quality permit and the commitments to keeping the roads watered.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Ben Grimes (Plateau)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White # 35 Date: 7/29/93