



inspection report

Partial Inspection Date: 11/2/94
 Complete Time: 8 : 30 am pm to 11 : 30 am pm
 Exploration Date of Last Inspection: 10/24/94

Mine Name: Starpoint County: Carbon Permit Number: ACT 007/006
Permittee and/or Operator's Name: Cyrus Mining
Business Address: P.O. Drawer, Park, Price, Ut, 84501
Type of Mining Activity: Underground Surface Prep. Plant Other
State Official(s): Bill Malencik
Company Official(s): Ralph Mooseman
Federal Official(s): N/A

Weather Conditions: Snowing - 8"-12" inches of snow on mine site
Existing Acreage: Permitted- 7200 Disturbed- 220 Regraded- _____ Seeded- _____ Bonded- 220
Increased/Decreased: Permitted- _____ Disturbed- _____ Regraded- _____ Seeded- _____ Bonded- _____
Status: Exploration / Active / Inactive / Temporary Cessation / Bond Forfeiture
 Reclamation (Phase I / Phase II / Final Bond Release / Liability _____ Year)

Followup Items

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

| | EVALUATED | N/A | COMMENTS | NOV/ENF |
|--|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. SIGNS AND MARKERS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. TOPSOIL | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. DIVERSIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| b. SEDIMENT PONDS AND IMPOUNDMENTS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| c. OTHER SEDIMENT CONTROL MEASURES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| d. WATER MONITORING | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| e. EFFLUENT LIMITATIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. EXPLOSIVES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. NONCOAL WASTE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. SLIDES AND OTHER DAMAGE | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 11. CONTEMPORANEOUS RECLAMATION | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. BACKFILLING AND GRADING | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. REVEGETATION | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 14. SUBSIDENCE CONTROL | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. CESSATION OF OPERATIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16. ROADS: | | | | |
| a. CONSTRUCTION/MAINTENANCE/SURFACING | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| b. DRAINAGE CONTROLS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 17. OTHER TRANSPORTATION FACILITIES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS CHECK (4th Quarter-April, May, June) _____ (date) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20. AIR QUALITY PERMIT | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 21. BONDING & INSURANCE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 11/21/94

Please number comments to correspond with topics on previous page.

General Comments. Weather conditions and snow on the mine site obscured most of the environmental control measures.

Topsoil. The topsoil pile by the transfer station is still not completed. The fence was partially removed as a result of storing additional topsoil material. If weather conditions are such that the topsoil activities planned cannot be completed the fence should be reinstalled.

Sediment Pond. Sediment ponds that were observed included ponds #2, 8 & 9. All contained runoff and were seed over

Slide. The slide project that was in the final stages of completion at the last inspection noted herein has been completed.

Mr. Mills was not at the mine site. Wrote a note to him pointing out seeds required in the approved plan that were not seeded on the slide area. Requested him to consider overseeding the missing species in the fall of 1995 since the slide reclamation plan was approved as final reclamation. Should he have questions, the note requested that he contact Susan White, or the undersigned. In event the missing species

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act/007/006

Inspection Date 11/21/91

Please number comments to correspond with topics on previous page.

are not seeded, this will place a cloud on this project and it may be considered contemporaneous and not final reclamation. A followup commitment is requested.

Road. The haul road and other roads were observed. Snow had been removed from the mine roads. The road adjacent to the slide area was reconstructed and blacktopped.

Copy of report mailed to CPMC/hon Mills & Ben Quinn; OSM/Marcia Potts; DOGM/J. Heltrich

Copy of report given to ^{filed PFO} _____

Inspector's signature Jim J. Heltrich No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE